

茨城県の放射線量の状況について(2月16日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	65	66	66	56	69	51	65
0:20	65	66	66	57	69	51	65
0:30	65	66	66	56	70	51	64
0:40	66	65	66	57	69	52	65
0:50	65	67	66	57	68	52	65
1:00	66	65	66	57	69	51	64
1:10	65	66	67	58	69	51	64
1:20	65	67	66	57	69	52	64
1:30	65	66	66	57	69	52	64
1:40	65	65	67	57	69	51	64
1:50	66	66	66	56	69	52	64
2:00	65	66	67	56	69	51	64
2:10	66	66	66	57	69	52	64
2:20	65	66	65	57	69	52	64
2:30	66	66	65	57	69	51	64
2:40	66	66	66	57	69	52	64
2:50	65	66	67	57	68	52	64
3:00	65	66	66	57	69	52	65
3:10	66	66	66	57	68	51	64
3:20	65	66	66	57	69	51	65
3:30	65	66	67	57	70	52	64
3:40	65	66	66	57	69	51	64
3:50	65	66	67	57	69	51	65
4:00	66	66	66	57	70	52	64
4:10	65	66	66	57	69	51	64
4:20	65	66	66	57	69	51	64
4:30	65	65	66	57	69	51	65
4:40	65	66	66	57	69	52	65
4:50	65	66	66	56	69	52	65
5:00	65	66	66	57	69	52	64
5:10	65	66	66	57	69	51	65
5:20	66	66	66	56	69	51	65
5:30	65	66	66	56	69	51	64
5:40	65	65	66	57	69	51	64
5:50	65	66	65	56	69	52	64
6:00	66	65	65	56	69	52	65
6:10	66	67	66	57	69	52	65
6:20	66	65	67	57	69	51	64
6:30	65	66	66	56	69	52	65
6:40	65	66	66	57	69	51	64
6:50	65	65	66	56	68	52	65
7:00	65	66	66	57	69	51	64
7:10	66	66	66	56	69	51	64
7:20	65	65	63	57	69	52	64
7:30	65	66	61	57	68	52	65
7:40	65	66	61	57	68	52	64
7:50	65	66	60	56	69	52	64
8:00	65	66	61	57	68	51	64
8:10	66	66	61	56	68	52	64
8:20	65	66	61	57	69	51	64
8:30	65	67	61	57	68	52	64
8:40	65	66	61	57	67	52	64
8:50	64	66	61	57	67	51	64
9:00	65	66	61	57	66	52	64
9:10	65	66	60	57	67	51	65
9:20	65	66	61	57	67	52	64
9:30	65	66	62	56	66	52	64
9:40	66	67	61	57	65	52	65
9:50	65	66	61	57	65	51	65
10:00	65	66	61	57	65	53	65
10:10	64	65	61	57	66	51	65
10:20	65	66	61	56	65	51	64
10:30	66	66	61	57	65	51	64
10:40	65	66	61	56	64	52	64
10:50	66	66	61	57	65	51	65
11:00	66	66	61	57	65	51	65
11:10	66	66	60	57	65	52	64
11:20	66	66	61	56	65	51	65
11:30	66	66	60	57	65	52	65
11:40	66	66	61	57	66	52	65
11:50	66	66	61	57	65	52	65
12:00	66	66	61	57	66	52	65

茨城県の放射線量の状況について(2月16日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	66	66	61	57	65	52	65
12:20	66	66	61	57	65	52	65
12:30	66	65	61	57	66	52	65
12:40	66	66	61	57	66	52	65
12:50	65	66	61	56	66	51	65
13:00	66	66	61	57	66	51	65
13:10	66	66	60	56	66	52	65
13:20	66	66	60	57	65	51	65
13:30	66	65	61	57	66	52	65
13:40	65	66	61	57	66	51	64
13:50	66	66	60	57	65	52	65
14:00	66	67	61	58	65	51	65
14:10	66	66	61	57	65	51	66
14:20	65	67	62	56	66	52	65
14:30	66	66	61	57	67	52	65
14:40	66	66	61	57	65	51	65
14:50	65	66	60	56	66	51	65
15:00	66	66	61	58	66	51	65
15:10	66	65	61	56	66	51	65
15:20	66	66	61	57	66	52	65
15:30	65	66	61	57	66	52	65
15:40	66	66	64	56	66	52	65
15:50	66	66	65	57	67	51	65
16:00	66	66	65	57	67	52	65
16:10	66	65	66	57	68	52	65
16:20	66	66	66	56	69	51	65
16:30	66	66	66	57	68	52	65
16:40	66	67	66	57	69	52	65
16:50	66	67	66	57	69	51	65
17:00	66	66	66	57	69	51	65
17:10	66	66	65	56	69	52	66
17:20	66	66	65	57	69	51	65
17:30	66	67	66	57	69	52	65
17:40	66	66	67	56	69	52	65
17:50	65	66	66	56	69	51	65
18:00	66	66	66	57	69	52	66
18:10	66	66	66	57	69	51	66
18:20	66	65	66	57	69	51	65
18:30	66	67	66	57	70	51	65
18:40	66	66	66	57	69	52	65
18:50	66	66	66	57	69	52	65
19:00	66	67	66	57	69	52	65
19:10	65	66	65	57	69	51	65
19:20	67	66	66	57	68	52	65
19:30	66	67	66	57	70	51	64
19:40	66	66	67	57	70	52	65
19:50	66	67	66	57	69	52	65
20:00	66	67	66	57	69	52	64
20:10	65	67	66	57	69	52	65
20:20	66	65	66	57	70	51	65
20:30	66	66	66	57	69	52	65
20:40	66	66	66	57	69	52	65
20:50	66	67	66	57	69	52	65
21:00	66	66	65	57	69	52	65
21:10	66	65	67	56	70	52	64
21:20	66	67	66	56	69	52	64
21:30	66	66	65	57	69	52	65
21:40	66	67	66	57	69	52	64
21:50	65	66	66	57	70	52	64
22:00	66	67	66	58	69	52	64
22:10	65	66	66	57	69	52	65
22:20	66	66	66	57	70	52	65
22:30	66	67	66	57	70	52	64
22:40	66	66	66	57	68	52	65
22:50	66	66	66	57	69	52	64
23:00	65	66	67	57	69	52	65
23:10	66	66	66	57	70	52	65
23:20	66	66	67	58	70	52	65
23:30	65	66	66	57	70	52	65
23:40	66	67	66	57	70	52	66
23:50	66	66	66	57	69	52	65
0:00	66	67	66	58	69	51	66

茨城県の放射線量の状況について(2月17日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	65	67	67	57	69	52	65
0:20	65	66	66	57	69	53	64
0:30	65	67	67	57	69	52	65
0:40	66	67	66	57	70	52	65
0:50	66	66	66	58	69	52	65
1:00	66	67	66	57	69	52	66
1:10	66	67	67	57	69	52	65
1:20	66	67	66	58	70	52	66
1:30	66	67	66	57	70	52	65
1:40	66	67	67	57	69	52	65
1:50	66	67	67	57	70	52	65
2:00	66	67	66	58	70	52	64
2:10	66	67	67	57	69	52	65
2:20	66	67	66	57	70	52	65
2:30	66	66	66	57	70	53	65
2:40	66	66	66	57	69	53	65
2:50	66	67	66	57	70	52	64
3:00	66	66	66	57	70	53	65
3:10	66	67	67	58	70	52	64
3:20	66	67	67	57	70	52	65
3:30	66	67	66	57	70	52	65
3:40	65	67	67	58	70	52	65
3:50	66	67	67	57	70	53	65
4:00	66	68	67	57	70	52	66
4:10	67	68	67	57	69	52	66
4:20	67	67	67	57	70	52	65
4:30	66	67	67	58	71	52	66
4:40	66	67	67	58	70	52	65
4:50	66	67	66	57	71	53	65
5:00	67	67	66	58	70	52	66
5:10	67	67	66	58	71	52	65
5:20	66	67	67	58	71	52	65
5:30	66	67	66	58	70	53	65
5:40	67	66	67	57	70	53	66
5:50	67	68	66	58	70	52	66
6:00	67	68	67	57	70	52	65
6:10	66	67	66	57	71	52	65
6:20	66	67	67	58	71	53	66
6:30	66	68	66	58	69	53	65
6:40	67	67	67	57	69	53	65
6:50	67	68	66	57	69	53	65
7:00	66	67	67	57	69	53	65
7:10	67	67	67	58	69	53	65
7:20	67	68	65	57	69	52	66
7:30	66	68	61	57	69	52	66
7:40	67	68	61	58	68	53	65
7:50	67	67	61	58	70	52	65
8:00	66	67	61	57	69	52	66
8:10	67	68	62	57	70	52	65
8:20	68	68	62	58	68	52	66
8:30	66	67	62	57	67	52	66
8:40	66	68	61	58	68	52	66
8:50	67	68	61	58	68	52	66
9:00	67	68	61	58	68	52	65
9:10	66	67	62	58	68	52	66
9:20	66	68	61	58	69	52	66
9:30	67	68	62	57	68	53	65
9:40	67	67	62	58	67	53	65
9:50	67	67	62	58	68	52	65
10:00	67	67	61	57	68	53	66
10:10	66	68	61	58	68	52	66
10:20	66	68	62	57	68	53	65
10:30	67	68	61	58	68	52	65
10:40	66	68	62	58	68	52	65
10:50	66	67	62	58	68	52	66
11:00	66	67	61	57	67	52	65
11:10	66	68	62	58	67	52	65
11:20	67	66	61	58	67	52	66
11:30	66	67	61	58	68	52	66
11:40	67	67	61	58	68	52	66
11:50	67	67	61	57	68	52	66
12:00	66	66	62	58	68	52	66

茨城県の放射線量の状況について(2月17日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	66	67	61	58	68	52	65
12:20	67	67	62	57	69	52	66
12:30	67	67	61	57	68	52	65
12:40	66	67	62	57	67	51	66
12:50	66	67	62	58	67	51	66
13:00	67	67	60	57	67	52	66
13:10	66	67	60	57	68	52	66
13:20	66	67	62	58	68	52	65
13:30	66	67	61	58	68	52	66
13:40	66	68	61	58	69	52	66
13:50	66	67	59	59	68	52	66
14:00	67	66	60	58	67	52	66
14:10	66	67	61	57	68	52	66
14:20	66	68	61	58	68	52	66
14:30	66	67	60	57	67	51	65
14:40	67	67	61	57	67	52	65
14:50	66	68	61	58	67	52	65
15:00	65	67	61	58	67	52	66
15:10	65	66	62	58	68	52	66
15:20	65	67	62	58	68	52	65
15:30	66	67	61	57	68	51	66
15:40	66	66	61	57	68	52	66
15:50	66	67	60	57	68	52	66
16:00	66	67	62	57	68	52	66
16:10	66	67	61	57	68	52	65
16:20	66	67	60	57	68	52	65
16:30	65	67	61	58	69	52	65
16:40	66	67	61	57	68	52	65
16:50	66	67	61	57	68	51	65
17:00	66	67	61	57	69	51	66
17:10	66	68	61	57	70	52	66
17:20	66	67	66	57	70	52	65
17:30	66	67	66	57	70	52	65
17:40	66	67	66	58	70	52	65
17:50	66	67	66	57	69	52	66
18:00	66	67	66	57	70	52	65
18:10	66	66	66	57	69	52	66
18:20	66	66	65	57	68	51	66
18:30	66	66	66	57	69	52	65
18:40	66	67	66	57	69	52	65
18:50	65	66	66	57	69	51	65
19:00	66	67	67	57	68	52	65
19:10	65	67	66	57	69	51	66
19:20	65	67	67	57	69	52	65
19:30	65	66	66	58	68	52	66
19:40	66	66	66	57	68	51	65
19:50	65	66	65	57	68	52	65
20:00	65	67	62	57	67	51	65
20:10	66	67	63	57	69	51	65
20:20	66	67	62	57	68	52	65
20:30	65	67	62	57	69	52	65
20:40	66	66	62	58	68	52	65
20:50	65	67	62	58	68	51	65
21:00	66	66	63	57	68	52	65
21:10	65	66	62	57	68	52	65
21:20	66	66	62	57	68	52	65
21:30	66	66	63	57	69	52	66
21:40	66	66	62	57	68	51	65
21:50	66	66	62	57	68	51	64
22:00	66	66	63	56	67	51	66
22:10	65	66	65	57	68	52	66
22:20	65	67	66	57	68	52	65
22:30	66	66	66	57	68	51	65
22:40	65	66	66	57	68	52	65
22:50	66	66	66	57	69	52	65
23:00	65	66	66	57	69	52	65
23:10	66	66	66	57	68	52	65
23:20	65	66	66	57	68	52	65
23:30	66	67	66	56	68	52	66
23:40	66	66	66	56	68	52	65
23:50	65	66	66	57	69	52	65
0:00	65	66	66	57	68	52	66

茨城県の放射線量の状況について(2月18日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	65	66	67	57	67	52	65
0:20	65	67	66	57	68	52	66
0:30	65	66	66	57	68	52	65
0:40	66	66	66	57	68	52	65
0:50	66	67	67	57	68	52	66
1:00	65	67	67	58	68	52	65
1:10	66	67	66	57	68	52	65
1:20	65	67	67	57	69	51	65
1:30	65	66	66	57	68	52	64
1:40	65	66	66	57	68	52	65
1:50	66	67	66	57	69	52	65
2:00	65	67	67	57	68	52	66
2:10	65	66	66	57	69	52	65
2:20	66	66	66	57	68	52	65
2:30	65	67	66	56	68	52	65
2:40	66	67	66	57	68	52	66
2:50	65	67	67	57	69	52	65
3:00	65	66	66	57	68	51	65
3:10	66	67	66	57	68	52	65
3:20	66	66	65	58	69	52	65
3:30	65	66	67	57	68	52	65
3:40	66	66	66	57	68	52	65
3:50	66	66	66	57	68	51	66
4:00	65	66	65	57	69	52	65
4:10	66	66	66	57	68	51	66
4:20	65	67	66	57	68	52	65
4:30	65	66	66	56	68	52	65
4:40	65	67	66	57	67	52	64
4:50	65	66	66	57	68	52	65
5:00	66	67	66	57	67	52	65
5:10	66	67	66	57	69	52	65
5:20	66	66	66	57	68	52	65
5:30	65	66	66	57	68	51	65
5:40	65	66	66	57	68	52	65
5:50	65	66	66	57	69	51	65
6:00	65	66	66	57	70	52	65
6:10	65	66	67	57	70	51	65
6:20	65	66	66	56	69	52	64
6:30	67	66	66	57	69	52	64
6:40	66	66	67	57	69	51	65
6:50	65	67	66	57	69	52	65
7:00	65	66	66	56	69	51	65
7:10	66	67	66	57	69	51	65
7:20	66	66	64	57	69	52	64
7:30	66	67	60	58	69	52	65
7:40	66	66	60	57	69	51	65
7:50	65	66	61	57	69	52	65
8:00	66	67	61	57	70	52	65
8:10	65	66	60	57	69	51	65
8:20	66	67	60	58	69	52	64
8:30	65	67	61	57	68	52	65
8:40	65	66	60	57	68	51	65
8:50	65	66	61	57	68	51	65
9:00	65	66	60	57	68	52	65
9:10	65	66	60	57	67	51	65
9:20	65	66	60	56	67	51	65
9:30	66	67	60	57	68	51	65
9:40	65	67	60	56	67	51	65
9:50	66	67	60	56	68	51	65
10:00	点検中	66	60	57	68	51	65
10:10	点検中	66	60	56	67	51	65
10:20	点検中	66	60	57	67	51	65
10:30	点検中	66	60	57	67	52	65
10:40	点検中	67	61	57	67	52	65
10:50	点検中	66	60	57	67	51	64
11:00	点検中	66	60	56	68	51	65
11:10	点検中	65	61	57	67	52	66
11:20	点検中	67	60	57	67	52	65
11:30	点検中	67	61	58	66	51	65
11:40	点検中	66	60	57	67	51	65
11:50	点検中	66	61	57	67	51	64
12:00	点検中	68	61	56	68	51	66

茨城県の放射線量の状況について(2月18日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	点検中	66	61	57	67	51	65
12:20	点検中	66	60	57	67	51	65
12:30	点検中	66	61	57	67	51	65
12:40	点検中	67	60	57	67	51	66
12:50	点検中	66	60	57	67	51	65
13:00	点検中	67	60	57	67	51	65
13:10	点検中	66	60	57	68	51	66
13:20	点検中	66	59	57	68	51	65
13:30	点検中	66	60	57	68	52	65
13:40	点検中	66	60	57	67	52	65
13:50	点検中	67	61	57	67	51	65
14:00	点検中	66	61	58	68	51	65
14:10	点検中	67	60	57	68	51	65
14:20	点検中	67	60	58	68	51	66
14:30	点検中	66	61	57	67	52	65
14:40	点検中	66	60	57	67	51	65
14:50	点検中	66	60	58	68	51	65
15:00	点検中	66	60	57	68	52	65
15:10	点検中	67	60	58	67	51	66
15:20	点検中	66	60	58	67	52	65
15:30	点検中	67	59	57	68	51	65
15:40	点検中	67	61	57	67	51	65
15:50	点検中	67	60	58	68	51	65
16:00	点検中	67	60	58	67	52	65
16:10	点検中	66	60	57	68	51	65
16:20	点検中	65	60	57	69	51	65
16:30	点検中	66	60	57	69	51	65
16:40	点検中	67	60	57	68	51	65
16:50	点検中	65	60	57	68	51	65
17:00	点検中	66	60	58	69	51	65
17:10	点検中	67	60	57	69	51	65
17:20	点検中	67	60	57	68	51	65
17:30	点検中	66	63	57	68	52	65
17:40	点検中	66	62	58	69	52	65
17:50	点検中	66	62	57	69	52	65
18:00	点検中	67	62	57	69	52	66
18:10	点検中	67	63	57	69	51	65
18:20	点検中	67	62	57	68	52	65
18:30	点検中	67	62	57	68	51	64
18:40	点検中	66	62	57	69	51	65
18:50	点検中	66	62	57	69	52	66
19:00	点検中	66	62	57	69	52	65
19:10	点検中	66	62	57	69	51	65
19:20	点検中	66	62	57	69	52	65
19:30	点検中	67	62	56	70	52	65
19:40	点検中	66	61	57	69	52	65
19:50	点検中	66	62	57	70	51	66
20:00	点検中	66	62	56	69	52	65
20:10	点検中	67	62	56	68	52	65
20:20	点検中	67	62	57	69	51	66
20:30	点検中	66	62	57	69	52	65
20:40	点検中	66	62	57	69	52	65
20:50	点検中	66	65	57	68	51	65
21:00	点検中	66	65	57	69	51	66
21:10	点検中	66	66	57	70	52	65
21:20	点検中	66	66	57	69	51	65
21:30	点検中	66	66	57	70	52	65
21:40	点検中	66	66	57	70	52	65
21:50	点検中	67	66	58	69	52	65
22:00	点検中	66	66	57	69	52	65
22:10	点検中	67	66	57	69	52	65
22:20	点検中	67	66	58	69	52	65
22:30	点検中	66	65	58	69	51	65
22:40	点検中	66	66	57	69	51	65
22:50	点検中	67	66	57	69	52	65
23:00	点検中	66	65	57	69	51	65
23:10	点検中	66	66	57	68	52	65
23:20	点検中	66	66	57	69	52	65
23:30	点検中	66	67	57	69	52	65
23:40	点検中	66	66	57	69	51	65
23:50	点検中	67	66	57	69	52	64
0:00	点検中	66	65	56	69	51	65

茨城県の放射線量の状況について(2月19日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	点検中	66	66	57	69	52	65
0:20	点検中	66	66	57	69	51	65
0:30	点検中	66	66	56	70	52	65
0:40	点検中	67	65	57	69	52	66
0:50	点検中	67	67	57	70	51	65
1:00	点検中	66	66	57	69	52	65
1:10	点検中	66	66	57	69	52	65
1:20	点検中	66	66	57	70	52	65
1:30	点検中	67	66	57	68	52	65
1:40	点検中	66	66	56	69	51	65
1:50	点検中	67	65	56	69	52	65
2:00	点検中	66	65	57	69	51	65
2:10	点検中	66	66	57	69	51	65
2:20	点検中	66	65	57	69	52	66
2:30	点検中	66	66	57	69	52	66
2:40	点検中	66	66	57	69	52	65
2:50	点検中	66	66	57	69	52	66
3:00	点検中	67	66	57	69	52	66
3:10	点検中	67	66	57	69	51	65
3:20	点検中	67	66	57	69	51	66
3:30	点検中	66	66	57	69	52	65
3:40	点検中	67	66	57	69	52	65
3:50	点検中	66	66	57	70	51	66
4:00	点検中	67	66	57	70	52	65
4:10	点検中	67	66	57	69	51	65
4:20	点検中	66	66	58	69	52	65
4:30	点検中	66	66	57	70	51	65
4:40	点検中	66	67	56	70	52	66
4:50	点検中	67	66	57	69	52	65
5:00	点検中	66	66	57	69	51	66
5:10	点検中	67	66	58	69	52	64
5:20	点検中	67	66	56	69	52	66
5:30	点検中	66	66	57	69	52	65
5:40	点検中	66	65	57	70	51	66
5:50	点検中	66	66	56	69	52	66
6:00	点検中	67	67	57	70	52	65
6:10	点検中	66	66	56	70	52	65
6:20	点検中	67	66	57	70	52	65
6:30	点検中	67	66	56	68	52	66
6:40	点検中	66	65	56	68	52	65
6:50	点検中	66	66	56	68	52	65
7:00	点検中	66	66	56	68	52	65
7:10	点検中	66	66	56	69	52	65
7:20	点検中	66	64	56	68	51	65
7:30	点検中	67	59	56	67	52	65
7:40	点検中	66	58	56	68	51	64
7:50	点検中	67	60	56	69	51	65
8:00	点検中	66	59	56	68	51	64
8:10	点検中	66	60	56	67	51	65
8:20	点検中	66	59	56	67	51	65
8:30	点検中	66	60	56	67	51	65
8:40	点検中	66	60	56	66	51	65
8:50	点検中	66	60	57	67	51	65
9:00	点検中	66	60	58	67	52	66
9:10	点検中	68	60	56	67	51	65
9:20	点検中	66	60	57	66	51	65
9:30	点検中	66	61	57	66	51	65
9:40	点検中	66	60	57	68	51	65
9:50	点検中	66	60	57	67	51	65
10:00	点検中	67	60	57	67	51	65
10:10	点検中	67	60	57	67	51	65
10:20	点検中	67	59	57	67	51	65
10:30	点検中	67	61	57	68	52	65
10:40	点検中	67	59	57	67	51	65
10:50	点検中	66	60	58	67	51	66
11:00	点検中	66	59	56	67	51	65
11:10	点検中	66	60	57	68	51	65
11:20	点検中	66	60	57	66	51	65
11:30	点検中	66	60	58	67	51	65
11:40	点検中	67	60	57	67	52	65
11:50	点検中	66	60	57	68	52	65
12:00	点検中	67	60	59	67	52	65

茨城県の放射線量の状況について(2月19日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	点検中	67	60	57	67	52	65
12:20	点検中	67	60	57	68	51	65
12:30	点検中	67	60	57	67	51	65
12:40	点検中	66	60	58	67	51	66
12:50	点検中	67	60	58	67	51	65
13:00	点検中	67	60	57	67	51	65
13:10	点検中	67	60	57	66	51	65
13:20	点検中	66	60	57	66	51	66
13:30	点検中	67	61	56	67	51	65
13:40	点検中	66	60	57	68	51	65
13:50	点検中	66	59	57	68	51	65
14:00	点検中	65	59	57	66	52	65
14:10	点検中	66	60	57	67	51	65
14:20	点検中	66	60	57	67	51	65
14:30	点検中	66	60	57	68	51	65
14:40	点検中	66	60	58	67	51	65
14:50	点検中	66	60	58	67	51	65
15:00	点検中	67	60	57	66	52	66
15:10	点検中	66	60	58	65	51	65
15:20	点検中	66	60	57	65	52	65
15:30	点検中	67	60	57	65	52	65
15:40	点検中	66	60	57	66	51	65
15:50	点検中	66	60	57	67	51	65
16:00	点検中	65	59	57	68	51	65
16:10	点検中	66	61	57	67	51	65
16:20	点検中	67	66	57	67	52	65
16:30	点検中	66	66	57	68	51	65
16:40	点検中	66	66	57	67	51	65
16:50	点検中	67	66	57	67	51	65
17:00	点検中	67	66	57	69	51	65
17:10	点検中	67	66	58	68	51	64
17:20	点検中	66	66	57	69	51	66
17:30	点検中	67	66	57	69	51	65
17:40	点検中	67	66	57	68	52	65
17:50	点検中	67	67	57	69	51	65
18:00	点検中	67	66	57	68	51	65
18:10	点検中	67	66	56	69	51	65
18:20	点検中	66	66	57	69	51	65
18:30	点検中	66	66	56	69	51	65
18:40	点検中	67	66	57	69	51	65
18:50	点検中	66	66	57	69	51	65
19:00	点検中	67	66	57	69	52	65
19:10	点検中	67	65	57	68	51	65
19:20	点検中	66	66	57	68	51	65
19:30	点検中	66	65	57	68	52	65
19:40	点検中	67	66	57	68	52	65
19:50	点検中	67	66	57	68	51	65
20:00	点検中	67	66	57	69	52	66
20:10	点検中	65	67	57	68	51	65
20:20	点検中	67	66	57	68	52	65
20:30	点検中	66	66	56	68	52	65
20:40	点検中	66	66	57	68	51	66
20:50	点検中	67	66	57	68	51	65
21:00	点検中	67	66	58	68	52	65
21:10	点検中	67	66	57	68	51	65
21:20	点検中	66	66	58	68	52	66
21:30	点検中	66	66	57	68	52	66
21:40	点検中	66	66	57	68	51	65
21:50	点検中	66	66	57	68	52	65
22:00	点検中	66	66	57	68	52	66
22:10	点検中	67	65	56	68	52	65
22:20	点検中	67	66	57	68	51	65
22:30	点検中	67	66	57	68	52	66
22:40	点検中	67	66	58	68	52	65
22:50	点検中	67	66	56	68	51	65
23:00	点検中	66	67	57	68	52	66
23:10	点検中	66	66	56	68	52	65
23:20	点検中	67	66	57	68	51	65
23:30	点検中	66	66	57	68	52	65
23:40	点検中	67	66	57	68	52	65
23:50	点検中	66	67	57	68	51	66
0:00	点検中	67	65	57	68	51	64

茨城県の放射線量の状況について(2月20日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	点検中	67	66	57	68	52	65
0:20	点検中	67	66	58	68	52	66
0:30	点検中	66	67	57	68	52	64
0:40	点検中	68	66	57	68	52	66
0:50	点検中	67	67	57	69	52	65
1:00	点検中	67	66	57	69	52	65
1:10	点検中	66	67	57	68	52	65
1:20	点検中	67	66	57	68	52	65
1:30	点検中	67	66	58	69	52	66
1:40	点検中	67	67	57	68	52	66
1:50	点検中	66	66	57	68	52	65
2:00	点検中	66	67	57	68	52	66
2:10	点検中	67	66	57	68	52	65
2:20	点検中	67	67	57	69	52	65
2:30	点検中	67	66	57	68	51	65
2:40	点検中	66	66	57	68	52	66
2:50	点検中	67	67	57	68	52	64
3:00	点検中	67	67	57	69	52	65
3:10	点検中	67	66	57	69	52	65
3:20	点検中	66	66	57	69	52	65
3:30	点検中	66	66	57	68	52	66
3:40	点検中	67	66	58	69	52	65
3:50	点検中	68	67	57	69	51	65
4:00	点検中	67	67	57	69	52	65
4:10	点検中	67	67	57	68	52	66
4:20	点検中	68	66	57	69	52	65
4:30	点検中	68	67	57	69	53	66
4:40	点検中	68	66	58	68	53	65
4:50	点検中	68	67	58	68	52	65
5:00	点検中	67	66	57	68	52	65
5:10	点検中	67	66	57	68	51	65
5:20	点検中	67	67	57	69	52	65
5:30	点検中	67	66	57	68	52	66
5:40	点検中	67	67	57	68	53	66
5:50	点検中	67	66	57	68	52	66
6:00	点検中	66	66	57	69	51	65
6:10	点検中	66	67	57	69	52	65
6:20	点検中	67	66	57	69	51	65
6:30	点検中	67	66	57	70	51	65
6:40	点検中	66	67	57	70	52	65
6:50	点検中	67	67	58	69	52	65
7:00	点検中	66	62	57	69	52	65
7:10	点検中	67	61	57	69	51	65
7:20	点検中	66	61	57	70	52	65
7:30	点検中	66	61	57	68	52	65
7:40	点検中	66	60	58	68	52	65
7:50	点検中	67	61	57	70	51	65
8:00	点検中	67	60	57	69	52	65
8:10	点検中	67	60	58	69	51	65
8:20	点検中	66	60	57	67	52	66
8:30	点検中	67	61	57	67	51	65
8:40	点検中	67	61	57	69	52	64
8:50	点検中	67	61	58	69	52	65
9:00	点検中	67	61	58	69	52	65
9:10	点検中	67	61	57	69	52	65
9:20	点検中	66	61	58	68	51	65
9:30	点検中	67	61	57	69	51	65
9:40	点検中	67	61	57	67	51	66
9:50	点検中	66	61	57	68	51	65
10:00	点検中	67	62	57	67	52	65
10:10	点検中	66	60	57	68	52	65
10:20	点検中	66	61	58	68	51	65
10:30	点検中	67	61	57	67	51	66
10:40	点検中	66	61	57	67	52	65
10:50	点検中	66	61	57	68	52	65
11:00	点検中	67	61	57	68	52	65
11:10	点検中	67	61	57	68	52	65
11:20	点検中	67	61	57	68	51	65
11:30	点検中	66	61	57	67	52	65
11:40	点検中	67	61	57	67	51	66
11:50	点検中	67	60	58	68	52	65
12:00	点検中	67	61	57	68	52	65

茨城県の放射線量の状況について(2月20日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	点検中	66	61	57	67	51	65
12:20	点検中	67	60	58	68	51	65
12:30	点検中	67	61	57	67	51	65
12:40	点検中	67	61	58	68	51	65
12:50	点検中	67	60	58	68	51	65
13:00	点検中	67	60	57	68	51	65
13:10	点検中	67	61	57	68	52	65
13:20	点検中	67	61	58	68	51	65
13:30	点検中	67	60	58	68	51	66
13:40	点検中	66	60	57	69	51	65
13:50	点検中	66	60	58	68	51	65
14:00	点検中	66	61	57	67	52	65
14:10	点検中	66	60	57	69	51	65
14:20	点検中	67	60	57	68	51	65
14:30	点検中	67	60	58	68	52	65
14:40	点検中	67	60	58	68	51	65
14:50	点検中	66	60	57	68	51	65
15:00	点検中	66	61	58	68	51	65
15:10	65	67	61	57	68	51	66
15:20	66	67	60	56	69	51	65
15:30	67	点検中	61	57	68	51	65
15:40	67	点検中	60	57	69	51	65
15:50	66	点検中	60	57	68	51	65
16:00	66	点検中	60	57	67	51	65
16:10	66	点検中	61	58	69	52	65
16:20	66	点検中	60	57	69	51	64
16:30	66	点検中	61	58	68	51	65
16:40	66	点検中	60	57	68	51	65
16:50	67	点検中	60	57	69	51	65
17:00	66	点検中	60	57	68	51	65
17:10	65	点検中	60	57	69	51	65
17:20	66	点検中	60	57	69	51	65
17:30	66	点検中	63	58	69	52	65
17:40	67	点検中	63	57	69	51	65
17:50	66	点検中	62	57	68	52	65
18:00	66	点検中	63	57	69	51	65
18:10	66	点検中	62	57	70	52	65
18:20	66	点検中	61	58	69	51	65
18:30	65	点検中	62	57	69	51	65
18:40	66	点検中	62	57	69	51	65
18:50	66	点検中	63	56	69	52	65
19:00	66	点検中	62	57	69	52	65
19:10	66	点検中	62	57	70	51	65
19:20	67	点検中	62	57	69	51	66
19:30	65	点検中	62	57	69	52	65
19:40	66	点検中	62	57	69	51	65
19:50	67	点検中	63	57	69	53	65
20:00	66	点検中	62	58	69	51	65
20:10	67	点検中	63	56	69	52	65
20:20	67	点検中	62	57	70	52	66
20:30	66	点検中	63	57	70	52	65
20:40	67	点検中	63	57	69	51	66
20:50	67	点検中	65	57	70	52	65
21:00	67	点検中	67	57	70	52	65
21:10	66	点検中	66	57	70	52	65
21:20	66	点検中	66	57	69	52	65
21:30	67	点検中	66	57	70	53	65
21:40	66	点検中	67	57	69	52	66
21:50	66	点検中	66	57	70	52	66
22:00	67	点検中	66	57	69	51	65
22:10	66	点検中	67	57	70	52	66
22:20	66	点検中	66	58	71	53	66
22:30	66	点検中	67	57	70	52	65
22:40	67	点検中	67	57	69	52	65
22:50	67	点検中	67	56	70	52	65
23:00	66	点検中	66	57	70	52	66
23:10	67	点検中	66	58	70	52	66
23:20	67	点検中	66	57	70	52	66
23:30	67	点検中	66	57	69	53	65
23:40	66	点検中	67	58	70	53	66
23:50	66	点検中	67	57	69	52	65
0:00	66	点検中	66	58	71	52	66

茨城県の放射線量の状況について(2月21日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	66	点検中	67	57	70	53	66
0:20	67	点検中	67	58	71	52	65
0:30	67	点検中	68	58	70	52	66
0:40	67	点検中	67	58	70	52	66
0:50	67	点検中	67	58	71	53	65
1:00	67	点検中	67	57	70	53	66
1:10	66	点検中	67	58	71	52	66
1:20	67	点検中	67	58	69	52	65
1:30	66	点検中	67	57	71	52	65
1:40	68	点検中	66	58	69	52	66
1:50	66	点検中	66	58	69	53	66
2:00	67	点検中	66	57	70	53	66
2:10	66	点検中	67	58	70	52	67
2:20	66	点検中	66	58	71	53	65
2:30	66	点検中	66	58	70	52	66
2:40	67	点検中	67	57	69	52	66
2:50	66	点検中	67	58	70	53	66
3:00	67	点検中	67	58	71	53	66
3:10	67	点検中	68	58	70	52	66
3:20	67	点検中	66	58	70	52	65
3:30	67	点検中	67	58	70	53	66
3:40	67	点検中	67	58	70	52	66
3:50	67	点検中	67	58	70	53	65
4:00	67	点検中	67	58	71	53	66
4:10	67	点検中	67	59	70	53	67
4:20	67	点検中	67	58	70	53	66
4:30	68	点検中	66	58	71	53	66
4:40	67	点検中	67	57	70	53	66
4:50	67	点検中	67	57	70	53	66
5:00	67	点検中	67	58	70	52	67
5:10	67	点検中	66	58	71	54	66
5:20	69	点検中	67	58	70	53	66
5:30	67	点検中	66	58	71	53	66
5:40	67	点検中	67	58	70	53	67
5:50	68	点検中	68	58	70	53	66
6:00	67	点検中	67	58	70	52	66
6:10	67	点検中	67	58	70	53	66
6:20	69	点検中	66	58	71	54	66
6:30	68	点検中	66	58	69	53	66
6:40	68	点検中	67	58	69	53	66
6:50	68	点検中	67	58	66	53	66
7:00	68	点検中	64	57	68	53	66
7:10	68	点検中	61	58	69	53	66
7:20	67	点検中	61	58	69	53	66
7:30	67	点検中	61	58	69	53	67
7:40	68	点検中	61	59	69	53	66
7:50	67	点検中	61	58	71	53	66
8:00	68	点検中	61	58	69	52	66
8:10	67	点検中	61	59	70	53	66
8:20	68	点検中	61	59	70	53	66
8:30	67	点検中	61	58	71	53	66
8:40	68	点検中	61	58	69	53	66
8:50	68	点検中	61	58	70	53	67
9:00	67	点検中	61	58	70	53	67
9:10	68	点検中	60	58	69	53	67
9:20	67	点検中	61	59	70	53	66
9:30	67	点検中	61	58	69	52	66
9:40	67	点検中	61	59	69	53	66
9:50	68	点検中	61	58	70	52	66
10:00	67	点検中	61	58	70	52	67
10:10	67	点検中	61	59	70	53	66
10:20	67	点検中	61	58	68	53	66
10:30	68	点検中	61	58	69	52	66
10:40	68	点検中	61	59	69	52	66
10:50	67	点検中	61	59	68	53	66
11:00	67	点検中	61	58	68	53	67
11:10	67	点検中	61	58	68	53	66
11:20	67	点検中	61	58	68	52	66
11:30	67	点検中	60	58	69	53	66
11:40	67	点検中	60	58	67	52	67
11:50	67	点検中	60	57	68	52	66
12:00	67	点検中	60	58	68	52	66

茨城県の放射線量の状況について(2月21日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	67	点検中	60	58	68	52	66
12:20	67	点検中	61	58	68	52	66
12:30	67	点検中	60	58	68	52	65
12:40	66	点検中	61	58	67	52	66
12:50	66	点検中	61	58	67	52	65
13:00	67	点検中	61	58	67	52	66
13:10	67	点検中	60	58	68	53	66
13:20	66	点検中	60	58	68	52	66
13:30	67	点検中	60	57	67	52	66
13:40	67	点検中	60	58	67	52	66
13:50	67	点検中	60	58	67	52	66
14:00	67	点検中	60	58	68	52	66
14:10	66	点検中	60	57	68	52	66
14:20	67	点検中	60	58	68	53	66
14:30	66	点検中	60	58	68	52	66
14:40	67	点検中	60	57	68	52	66
14:50	67	点検中	60	57	69	52	66
15:00	67	点検中	59	58	69	51	66
15:10	66	点検中	60	58	68	52	65
15:20	66	点検中	60	57	67	52	66
15:30	67	点検中	59	58	68	52	66
15:40	67	点検中	60	57	68	52	66
15:50	66	点検中	60	58	69	51	66
16:00	66	点検中	60	57	68	52	66
16:10	67	点検中	61	57	69	52	66
16:20	67	点検中	60	59	69	51	66
16:30	67	点検中	60	58	69	51	66
16:40	67	点検中	60	58	68	52	66
16:50	66	点検中	61	58	69	52	66
17:00	66	点検中	60	58	68	51	65
17:10	66	点検中	60	58	70	51	66
17:20	66	点検中	60	58	70	52	65
17:30	66	点検中	60	57	69	52	65
17:40	66	点検中	60	57	70	52	65
17:50	66	点検中	60	57	68	52	65
18:00	66	点検中	60	57	69	51	66
18:10	66	点検中	65	57	70	52	65
18:20	66	点検中	65	57	69	52	65
18:30	66	点検中	66	57	69	52	66
18:40	66	点検中	66	57	69	51	65
18:50	66	点検中	66	57	69	51	65
19:00	66	点検中	66	57	70	51	66
19:10	66	点検中	65	57	69	52	66
19:20	66	点検中	66	58	69	51	66
19:30	66	点検中	66	57	68	52	66
19:40	66	点検中	66	58	68	51	66
19:50	66	点検中	66	57	68	51	64
20:00	66	点検中	66	57	68	52	66
20:10	66	点検中	66	57	68	52	65
20:20	65	点検中	66	57	69	52	65
20:30	66	点検中	66	57	68	52	65
20:40	66	点検中	66	58	67	51	66
20:50	66	点検中	65	57	68	52	66
21:00	66	点検中	66	57	68	52	65
21:10	66	点検中	66	57	68	51	66
21:20	66	点検中	66	57	68	52	65
21:30	66	点検中	66	57	68	52	65
21:40	66	点検中	66	57	68	51	65
21:50	66	点検中	66	57	68	51	65
22:00	66	点検中	66	57	68	52	65
22:10	66	点検中	66	57	67	51	66
22:20	66	点検中	66	57	67	52	65
22:30	66	点検中	66	57	68	51	65
22:40	66	点検中	67	57	68	51	66
22:50	66	点検中	66	57	68	51	65
23:00	66	点検中	66	57	68	51	65
23:10	67	点検中	66	57	69	52	65
23:20	65	点検中	66	57	69	52	65
23:30	66	点検中	66	57	69	51	65
23:40	66	点検中	67	57	69	52	66
23:50	66	点検中	66	58	69	52	65
0:00	66	点検中	66	57	68	52	64

茨城県の放射線量の状況について(2月22日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	66	点検中	66	57	68	51	65
0:20	66	点検中	66	57	69	52	65
0:30	66	点検中	67	57	69	52	65
0:40	66	点検中	67	57	69	52	66
0:50	66	点検中	66	57	69	52	65
1:00	66	点検中	66	57	69	52	65
1:10	66	点検中	67	58	69	52	65
1:20	66	点検中	66	57	69	52	65
1:30	66	点検中	66	58	69	52	65
1:40	66	点検中	66	57	69	52	65
1:50	66	点検中	66	57	69	52	65
2:00	66	点検中	67	58	69	52	65
2:10	66	点検中	66	58	70	52	66
2:20	66	点検中	66	57	69	52	65
2:30	67	点検中	66	57	69	52	65
2:40	66	点検中	66	57	70	53	65
2:50	67	点検中	67	58	70	52	66
3:00	66	点検中	66	57	69	52	65
3:10	66	点検中	67	57	70	51	65
3:20	66	点検中	67	58	69	52	66
3:30	66	点検中	66	57	70	52	65
3:40	67	点検中	67	58	70	52	65
3:50	67	点検中	67	58	70	52	66
4:00	67	点検中	67	57	69	52	65
4:10	66	点検中	66	58	70	52	65
4:20	67	点検中	66	58	70	53	66
4:30	66	点検中	67	58	70	52	66
4:40	66	点検中	67	58	69	53	66
4:50	67	点検中	67	58	70	53	66
5:00	67	点検中	67	57	70	52	65
5:10	67	点検中	67	58	69	52	65
5:20	67	点検中	66	57	70	53	65
5:30	67	点検中	67	57	70	52	66
5:40	67	点検中	67	57	70	52	65
5:50	67	点検中	66	57	70	53	65
6:00	67	点検中	68	57	70	53	65
6:10	66	点検中	68	58	70	53	66
6:20	67	点検中	66	58	70	52	66
6:30	67	点検中	67	58	70	53	65
6:40	68	点検中	67	58	69	52	65
6:50	67	点検中	66	57	70	53	66
7:00	67	点検中	66	59	70	53	66
7:10	68	点検中	62	58	70	54	65
7:20	67	点検中	61	57	69	53	66
7:30	67	点検中	61	58	69	53	66
7:40	67	点検中	60	58	70	53	65
7:50	67	点検中	61	58	70	53	66
8:00	68	点検中	61	58	71	52	65
8:10	67	点検中	61	59	69	53	65
8:20	67	点検中	61	58	68	53	66
8:30	66	点検中	61	58	68	53	66
8:40	67	点検中	61	57	69	52	66
8:50	66	点検中	61	58	68	53	65
9:00	67	点検中	60	58	68	52	66
9:10	67	点検中	60	57	68	52	65
9:20	67	点検中	61	58	68	52	65
9:30	66	点検中	62	57	67	52	66
9:40	66	点検中	61	57	67	52	65
9:50	66	点検中	61	58	67	52	65
10:00	66	点検中	61	58	66	52	65
10:10	66	点検中	60	58	67	52	66
10:20	66	点検中	61	58	67	52	65
10:30	66	点検中	60	57	66	52	66
10:40	67	点検中	61	57	66	52	66
10:50	67	点検中	60	58	66	53	66
11:00	67	点検中	61	58	66	52	66
11:10	67	点検中	61	57	66	52	66
11:20	67	点検中	61	57	67	52	66
11:30	67	点検中	60	58	67	53	66
11:40	67	点検中	61	57	67	52	66
11:50	67	点検中	60	58	66	52	66
12:00	67	点検中	60	58	66	52	66

茨城県の放射線量の状況について(2月22日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	67	点検中	60	57	66	51	66
12:20	66	点検中	61	58	67	52	66
12:30	67	点検中	61	58	66	52	66
12:40	67	点検中	60	58	66	52	65
12:50	67	点検中	61	58	67	52	66
13:00	67	点検中	60	59	67	52	65
13:10	67	点検中	60	57	66	52	65
13:20	67	点検中	61	58	67	52	66
13:30	66	点検中	61	58	67	52	65
13:40	68	点検中	60	57	67	53	66
13:50	67	点検中	60	57	67	52	65
14:00	67	点検中	60	58	67	51	66
14:10	67	点検中	60	57	67	52	65
14:20	67	点検中	60	57	68	52	65
14:30	67	点検中	60	57	67	52	66
14:40	68	点検中	61	57	66	52	65
14:50	66	点検中	60	57	66	53	65
15:00	67	点検中	59	58	66	52	66
15:10	67	点検中	60	57	66	53	65
15:20	67	点検中	61	58	66	52	65
15:30	66	点検中	60	57	66	52	65
15:40	66	点検中	61	57	68	52	65
15:50	66	点検中	60	58	67	53	65
16:00	66	点検中	61	57	68	52	66
16:10	66	点検中	65	56	68	52	66
16:20	66	点検中	66	57	69	51	65
16:30	66	点検中	66	57	69	52	66
16:40	66	点検中	65	57	69	52	65
16:50	67	点検中	66	57	69	52	66
17:00	67	点検中	65	57	68	52	65
17:10	65	点検中	65	57	68	52	65
17:20	66	点検中	65	57	68	53	65
17:30	65	点検中	66	57	69	52	65
17:40	66	点検中	65	58	68	52	64
17:50	66	点検中	65	57	69	51	65
18:00	66	点検中	65	57	69	52	65
18:10	66	点検中	65	56	69	52	65
18:20	66	点検中	65	57	69	52	65
18:30	66	点検中	66	56	69	53	65
18:40	67	点検中	66	57	69	52	65
18:50	67	点検中	66	57	69	52	65
19:00	67	点検中	66	57	69	52	65
19:10	66	点検中	66	57	69	52	65
19:20	65	点検中	66	56	70	52	65
19:30	66	点検中	66	57	69	52	65
19:40	66	点検中	66	57	69	51	66
19:50	66	点検中	66	57	69	52	65
20:00	66	点検中	66	57	70	52	65
20:10	66	点検中	66	58	69	52	65
20:20	66	点検中	66	57	69	52	65
20:30	66	点検中	66	57	69	52	65
20:40	66	点検中	66	57	69	52	66
20:50	66	点検中	66	57	69	52	65
21:00	67	点検中	65	57	69	52	66
21:10	66	点検中	67	57	69	52	66
21:20	66	点検中	66	58	69	52	65
21:30	65	点検中	66	57	69	52	65
21:40	66	点検中	67	57	70	52	66
21:50	65	点検中	66	58	69	52	66
22:00	66	点検中	66	57	70	52	66
22:10	66	点検中	66	58	70	52	65
22:20	66	点検中	67	58	69	52	65
22:30	66	点検中	66	57	70	52	65
22:40	66	点検中	66	57	70	52	65
22:50	66	点検中	66	57	69	52	66
23:00	66	点検中	67	56	69	52	65
23:10	66	点検中	66	57	69	52	66
23:20	66	点検中	67	57	69	52	66
23:30	66	点検中	67	57	69	52	65
23:40	66	点検中	66	57	68	52	66
23:50	65	点検中	67	57	68	52	65
0:00	66	点検中	66	57	68	53	65

茨城県の放射線量の状況について(2月23日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	66	点検中	66	58	69	52	65
0:20	66	点検中	66	57	70	52	65
0:30	66	点検中	66	57	69	51	65
0:40	65	点検中	67	57	69	52	66
0:50	66	点検中	66	57	70	51	66
1:00	66	点検中	67	57	69	52	66
1:10	66	点検中	66	57	69	52	66
1:20	65	点検中	66	57	70	52	66
1:30	66	点検中	66	57	70	51	65
1:40	66	点検中	66	57	69	52	65
1:50	66	点検中	67	57	69	52	65
2:00	66	点検中	67	57	69	52	65
2:10	66	点検中	66	57	70	52	66
2:20	66	点検中	66	57	70	53	66
2:30	66	点検中	67	58	70	53	65
2:40	66	点検中	66	57	69	52	65
2:50	66	点検中	67	57	70	53	65
3:00	66	点検中	67	57	70	52	65
3:10	67	点検中	67	57	70	52	65
3:20	66	点検中	66	57	70	52	66
3:30	66	点検中	66	57	70	52	65
3:40	66	点検中	66	57	70	52	66
3:50	66	点検中	66	57	69	52	66
4:00	66	点検中	66	58	70	52	66
4:10	66	点検中	67	57	69	52	65
4:20	66	点検中	66	57	70	52	65
4:30	65	点検中	66	57	70	53	65
4:40	66	点検中	67	57	70	52	65
4:50	66	点検中	66	57	70	52	65
5:00	66	点検中	66	58	70	51	65
5:10	67	点検中	67	57	70	52	66
5:20	66	点検中	67	57	70	52	65
5:30	66	点検中	67	57	70	51	66
5:40	66	点検中	67	58	70	52	66
5:50	66	点検中	67	58	70	52	66
6:00	66	点検中	66	57	69	52	67
6:10	66	点検中	66	58	70	53	66
6:20	66	点検中	66	57	70	52	66
6:30	66	点検中	67	57	69	52	65
6:40	66	点検中	66	58	69	52	66
6:50	66	点検中	66	58	70	52	65
7:00	66	点検中	67	57	69	52	65
7:10	66	点検中	67	58	69	52	65
7:20	66	点検中	66	57	69	52	66
7:30	66	点検中	66	58	69	52	65
7:40	67	点検中	66	57	68	52	65
7:50	66	点検中	66	58	69	53	66
8:00	66	点検中	66	57	70	53	66
8:10	66	点検中	66	58	69	52	66
8:20	66	点検中	66	58	69	52	66
8:30	66	点検中	66	58	67	53	65
8:40	66	点検中	66	58	66	53	65
8:50	67	点検中	66	58	67	52	65
9:00	67	点検中	66	57	67	53	66
9:10	66	点検中	66	57	67	52	65
9:20	67	点検中	66	58	68	52	65
9:30	66	点検中	66	57	67	52	65
9:40	66	点検中	66	57	67	52	65
9:50	66	点検中	67	57	67	53	66
10:00	66	点検中	66	55	68	52	65
10:10	66	点検中	66	55	67	52	66
10:20	67	点検中	67	56	67	52	65
10:30	66	点検中	66	55	66	53	66
10:40	67	点検中	66	55	67	52	66
10:50	67	点検中	66	55	66	52	66
11:00	67	点検中	66	56	66	52	65
11:10	67	点検中	66	58	66	52	65
11:20	66	点検中	67	57	65	52	65
11:30	67	点検中	67	57	66	52	66
11:40	66	点検中	67	58	66	53	65
11:50	66	点検中	66	57	67	52	66
12:00	67	点検中	67	57	66	52	66

茨城県の放射線量の状況について(2月23日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	67	点検中	66	57	66	52	66
12:20	67	点検中	67	57	66	53	66
12:30	66	点検中	66	57	65	52	66
12:40	66	点検中	66	57	65	52	65
12:50	67	点検中	67	57	67	53	66
13:00	66	点検中	67	57	67	52	66
13:10	66	点検中	67	58	67	52	65
13:20	66	点検中	66	58	66	52	66
13:30	66	点検中	66	57	66	52	65
13:40	67	点検中	66	57	67	52	66
13:50	66	点検中	66	57	66	52	66
14:00	67	点検中	66	57	66	52	65
14:10	67	点検中	66	57	67	51	66
14:20	66	点検中	67	57	67	52	66
14:30	66	点検中	66	57	67	53	65
14:40	66	点検中	67	57	67	52	65
14:50	67	点検中	66	58	66	52	65
15:00	66	点検中	66	58	67	52	66
15:10	66	点検中	66	57	68	52	65
15:20	67	点検中	66	57	69	52	66
15:30	67	点検中	66	57	67	51	65
15:40	67	点検中	66	57	68	52	66
15:50	67	点検中	66	57	67	52	65
16:00	66	点検中	67	57	67	52	66
16:10	66	点検中	67	57	67	52	66
16:20	67	点検中	66	58	68	53	65
16:30	66	点検中	65	58	69	52	66
16:40	66	点検中	66	58	69	52	65
16:50	67	点検中	66	57	69	52	65
17:00	66	点検中	66	57	69	53	66
17:10	67	点検中	67	57	68	53	65
17:20	67	点検中	66	57	68	52	65
17:30	67	点検中	65	58	68	52	66
17:40	67	点検中	65	57	69	52	65
17:50	67	点検中	66	57	68	52	65
18:00	66	点検中	66	56	69	52	64
18:10	67	点検中	67	56	68	52	66
18:20	67	点検中	66	56	69	52	66
18:30	67	点検中	66	57	70	52	65
18:40	66	点検中	66	57	69	52	65
18:50	67	点検中	66	57	69	52	65
19:00	66	点検中	66	57	69	51	66
19:10	66	点検中	66	57	69	52	65
19:20	66	点検中	67	57	69	52	65
19:30	67	点検中	66	56	70	52	64
19:40	66	点検中	66	57	69	52	65
19:50	66	点検中	66	57	69	52	65
20:00	66	点検中	66	57	69	52	65
20:10	67	点検中	66	57	69	52	65
20:20	67	点検中	66	57	68	51	65
20:30	67	点検中	66	56	70	51	65
20:40	66	点検中	65	57	69	52	65
20:50	66	点検中	66	57	70	52	66
21:00	66	点検中	66	57	69	52	65
21:10	66	点検中	66	57	69	51	66
21:20	66	点検中	66	58	69	52	66
21:30	67	点検中	66	57	69	52	65
21:40	66	点検中	66	57	70	51	65
21:50	67	点検中	66	57	69	51	66
22:00	67	点検中	67	57	69	53	65
22:10	66	点検中	66	57	69	52	66
22:20	66	点検中	65	58	70	52	65
22:30	66	点検中	66	57	69	52	66
22:40	67	点検中	66	56	69	52	65
22:50	67	点検中	66	57	70	52	65
23:00	67	点検中	66	57	70	53	65
23:10	66	点検中	66	58	70	52	66
23:20	67	点検中	67	57	70	52	66
23:30	67	点検中	67	57	70	53	66
23:40	67	点検中	67	58	69	51	65
23:50	67	点検中	67	57	69	52	65
0:00	67	点検中	67	57	70	53	65

茨城県の放射線量の状況について(2月24日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	67	点検中	66	58	69	52	65
0:20	66	点検中	67	57	69	52	66
0:30	67	点検中	66	57	70	52	65
0:40	67	点検中	67	58	69	52	66
0:50	67	点検中	66	57	69	52	66
1:00	66	点検中	67	57	69	52	65
1:10	67	点検中	66	57	70	52	65
1:20	66	点検中	66	58	70	52	65
1:30	67	点検中	66	58	70	52	66
1:40	66	点検中	66	58	69	52	66
1:50	66	点検中	67	57	70	52	65
2:00	66	点検中	66	58	70	53	66
2:10	66	点検中	67	58	70	53	65
2:20	66	点検中	67	57	70	52	66
2:30	67	点検中	67	58	70	52	65
2:40	66	点検中	67	57	70	53	66
2:50	67	点検中	67	57	69	53	65
3:00	66	点検中	67	58	70	52	66
3:10	66	点検中	67	58	69	52	66
3:20	67	点検中	67	58	69	52	66
3:30	67	点検中	67	57	70	52	66
3:40	67	点検中	67	58	70	52	66
3:50	66	点検中	67	58	71	52	65
4:00	67	点検中	67	58	70	52	66
4:10	66	点検中	67	58	69	52	66
4:20	67	点検中	67	58	69	53	66
4:30	68	点検中	67	57	70	52	65
4:40	67	点検中	67	58	70	52	66
4:50	67	点検中	67	57	70	52	66
5:00	67	点検中	67	58	70	54	66
5:10	67	点検中	67	58	71	53	66
5:20	67	点検中	67	57	70	53	65
5:30	67	点検中	66	57	70	53	66
5:40	68	点検中	67	58	70	53	66
5:50	67	点検中	67	58	70	52	66
6:00	67	点検中	67	59	70	52	66
6:10	67	点検中	66	58	69	53	66
6:20	67	点検中	66	58	70	53	66
6:30	67	点検中	66	57	69	52	65
6:40	68	点検中	66	58	68	53	66
6:50	66	点検中	66	58	68	53	66
7:00	66	点検中	65	57	69	53	66
7:10	67	点検中	66	58	69	52	66
7:20	67	点検中	65	57	68	52	65
7:30	67	点検中	61	57	68	52	66
7:40	67	点検中	60	58	68	51	65
7:50	67	点検中	60	57	69	51	65
8:00	67	点検中	61	57	69	52	65
8:10	67	点検中	61	57	70	52	66
8:20	66	点検中	60	58	69	52	66
8:30	67	点検中	60	57	69	53	66
8:40	67	点検中	61	56	70	52	66
8:50	67	点検中	60	57	69	52	65
9:00	67	点検中	60	56	68	53	66
9:10	67	点検中	61	57	69	52	66
9:20	68	点検中	60	57	68	52	66
9:30	67	点検中	61	58	68	53	65
9:40	66	点検中	61	57	69	52	66
9:50	66	点検中	60	57	68	51	65
10:00	67	点検中	61	57	69	52	65
10:10	66	点検中	60	57	68	51	66
10:20	67	点検中	60	57	68	52	65
10:30	66	点検中	61	57	68	51	65
10:40	66	点検中	60	57	67	52	65
10:50	66	点検中	60	57	67	52	65
11:00	66	点検中	60	57	67	51	65
11:10	67	点検中	61	57	68	52	65
11:20	67	点検中	60	58	67	52	66
11:30	66	点検中	60	57	67	52	65
11:40	66	点検中	60	58	68	52	66
11:50	66	点検中	60	58	67	51	65
12:00	66	点検中	60	58	67	51	66

茨城県の放射線量の状況について(2月24日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	66	点検中	61	57	68	52	65
12:20	66	点検中	61	57	67	52	66
12:30	66	点検中	61	57	68	52	65
12:40	66	点検中	61	57	68	51	65
12:50	66	点検中	60	57	68	51	66
13:00	66	点検中	61	57	67	52	66
13:10	67	点検中	60	58	67	51	65
13:20	66	点検中	60	58	68	51	65
13:30	66	点検中	60	57	68	51	65
13:40	66	点検中	60	57	68	51	66
13:50	67	点検中	61	57	69	51	65
14:00	67	点検中	60	57	69	51	66
14:10	67	点検中	60	57	69	52	66
14:20	67	点検中	60	57	67	51	65
14:30	66	点検中	60	58	67	51	65
14:40	67	点検中	60	57	67	51	66
14:50	67	点検中	61	58	67	52	65
15:00	66	点検中	60	57	68	51	66
15:10	66	点検中	60	57	67	51	65
15:20	66	点検中	59	57	68	52	66
15:30	66	点検中	59	57	68	51	65
15:40	67	点検中	点検中	57	68	51	65
15:50	66	点検中	点検中	57	69	51	65
16:00	66	点検中	点検中	58	68	52	66
16:10	66	点検中	点検中	56	68	52	65
16:20	67	点検中	点検中	57	69	52	65
16:30	66	点検中	点検中	58	68	52	65
16:40	66	点検中	点検中	57	68	51	65
16:50	66	点検中	点検中	57	69	51	65
17:00	66	点検中	点検中	57	70	52	65
17:10	66	点検中	点検中	57	68	52	65
17:20	67	点検中	点検中	57	69	51	66
17:30	66	点検中	点検中	57	68	51	65
17:40	66	点検中	点検中	57	68	52	65
17:50	65	点検中	点検中	58	69	51	66
18:00	66	点検中	点検中	57	69	51	65
18:10	65	点検中	点検中	58	69	50	65
18:20	66	点検中	点検中	57	69	52	65
18:30	66	点検中	点検中	57	69	51	65
18:40	66	点検中	点検中	57	69	52	65
18:50	66	点検中	点検中	57	69	52	65
19:00	66	点検中	点検中	56	69	52	65
19:10	66	点検中	点検中	57	69	51	65
19:20	66	点検中	点検中	57	69	52	66
19:30	66	点検中	点検中	57	69	52	66
19:40	66	点検中	点検中	57	68	51	66
19:50	66	点検中	点検中	57	69	52	65
20:00	66	点検中	点検中	57	69	52	66
20:10	67	点検中	点検中	57	70	52	66
20:20	66	点検中	点検中	58	70	52	66
20:30	67	点検中	点検中	58	70	52	66
20:40	67	点検中	点検中	57	69	52	66
20:50	66	点検中	点検中	57	69	52	65
21:00	66	点検中	点検中	56	69	52	65
21:10	66	点検中	点検中	58	70	52	66
21:20	67	点検中	点検中	58	69	52	66
21:30	66	点検中	点検中	57	70	52	66
21:40	66	点検中	点検中	58	70	52	65
21:50	67	点検中	点検中	57	69	52	66
22:00	66	点検中	点検中	57	70	52	66
22:10	67	点検中	点検中	57	70	53	66
22:20	67	点検中	点検中	57	70	52	66
22:30	66	点検中	点検中	57	70	53	66
22:40	66	点検中	点検中	58	69	52	66
22:50	67	点検中	点検中	57	69	52	65
23:00	66	点検中	点検中	58	70	52	66
23:10	67	点検中	点検中	57	69	52	66
23:20	67	点検中	点検中	57	69	52	66
23:30	67	点検中	点検中	57	70	52	66
23:40	67	点検中	点検中	58	70	53	67
23:50	67	点検中	点検中	58	70	52	66
0:00	68	点検中	点検中	57	70	53	66

茨城県の放射線量の状況について(2月25日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
0:10	67	点検中	点検中	58	69	53	67
0:20	68	点検中	点検中	58	70	53	66
0:30	66	点検中	点検中	58	70	52	67
0:40	67	点検中	点検中	58	68	53	67
0:50	68	点検中	点検中	57	69	52	66
1:00	68	点検中	点検中	57	68	52	66
1:10	67	点検中	点検中	58	69	52	66
1:20	67	点検中	点検中	58	68	53	66
1:30	67	点検中	点検中	58	68	53	67
1:40	67	点検中	点検中	59	68	53	67
1:50	68	点検中	点検中	58	68	53	67
2:00	68	点検中	点検中	58	69	53	67
2:10	68	点検中	点検中	58	68	53	67
2:20	68	点検中	点検中	58	69	53	66
2:30	67	点検中	点検中	59	69	53	66
2:40	68	点検中	点検中	58	69	53	67
2:50	68	点検中	点検中	58	69	54	66
3:00	69	点検中	点検中	59	69	53	66
3:10	68	点検中	点検中	57	69	53	67
3:20	67	点検中	点検中	59	68	53	66
3:30	68	点検中	点検中	58	69	54	67
3:40	67	点検中	点検中	57	69	53	67
3:50	67	点検中	点検中	57	69	54	66
4:00	67	点検中	点検中	58	69	53	66
4:10	68	点検中	点検中	59	69	53	67
4:20	67	点検中	点検中	58	68	53	66
4:30	68	点検中	点検中	57	70	53	66
4:40	68	点検中	点検中	58	69	53	66
4:50	68	点検中	点検中	58	69	53	66
5:00	67	点検中	点検中	58	69	54	66
5:10	68	点検中	点検中	58	69	53	66
5:20	67	点検中	点検中	58	69	54	65
5:30	68	点検中	点検中	58	69	53	66
5:40	67	点検中	点検中	58	69	53	66
5:50	68	点検中	点検中	58	68	53	67
6:00	68	点検中	点検中	59	68	53	67
6:10	67	点検中	点検中	58	68	53	66
6:20	68	点検中	点検中	59	68	54	67
6:30	68	点検中	点検中	59	69	54	67
6:40	68	点検中	点検中	58	69	53	66
6:50	67	点検中	点検中	59	69	53	67
7:00	68	点検中	点検中	58	69	53	67
7:10	67	点検中	点検中	58	68	53	67
7:20	67	点検中	点検中	58	68	53	66
7:30	67	点検中	点検中	59	67	53	67
7:40	68	点検中	点検中	59	68	53	66
7:50	68	点検中	点検中	59	71	53	66
8:00	67	点検中	点検中	58	70	53	66
8:10	68	点検中	点検中	59	70	53	66
8:20	68	点検中	点検中	58	70	53	66
8:30	67	点検中	点検中	59	69	53	67
8:40	68	点検中	点検中	58	68	53	66
8:50	67	点検中	点検中	58	68	52	67
9:00	67	点検中	点検中	59	69	52	66
9:10	67	点検中	点検中	58	70	52	66
9:20	67	点検中	点検中	58	69	52	67
9:30	67	点検中	点検中	58	69	52	66
9:40	67	点検中	点検中	58	70	51	66
9:50	66	点検中	点検中	57	69	52	66
10:00	67	点検中	点検中	58	67	52	66
10:10	67	点検中	点検中	58	68	52	66
10:20	66	点検中	点検中	57	68	52	66
10:30	67	点検中	点検中	58	67	52	65
10:40	67	点検中	点検中	58	68	52	65
10:50	67	点検中	点検中	58	68	52	66
11:00	67	点検中	点検中	57	67	51	66
11:10	67	点検中	点検中	57	67	51	66
11:20	67	点検中	点検中	57	68	52	65
11:30	67	点検中	点検中	58	68	52	66
11:40	67	点検中	点検中	58	68	51	66
11:50	67	点検中	点検中	58	68	52	66
12:00	67	点検中	点検中	58	67	52	65

茨城県の放射線量の状況について(2月25日)
(固定観測局(東海村))

時刻	東海村						
	石神	豊岡	舟石川	押延	村松	三菱原燃	原燃工
12:10	67	点検中	点検中	58	67	52	66
12:20	67	点検中	点検中	58	67	52	67
12:30	67	点検中	点検中	58	68	52	65
12:40	67	点検中	点検中	58	68	52	66
12:50	67	点検中	点検中	58	67	52	66
13:00	67	点検中	点検中	58	66	52	66
13:10	67	点検中	点検中	58	69	52	66
13:20	67	点検中	点検中	58	69	52	66
13:30	67	点検中	点検中	58	68	53	66
13:40	67	点検中	点検中	58	68	52	66
13:50	67	点検中	点検中	58	68	53	66
14:00	67	点検中	点検中	58	68	52	66
14:10	66	点検中	点検中	58	68	52	66
14:20	66	点検中	点検中	58	67	52	66
14:30	67	点検中	点検中	57	67	52	65
14:40	66	点検中	点検中	57	68	53	66
14:50	66	点検中	点検中	58	68	52	66
15:00	66	点検中	点検中	57	67	52	65
15:10	66	点検中	点検中	58	67	52	65
15:20	67	点検中	点検中	58	69	52	66
15:30	66	点検中	点検中	57	69	52	66
15:40	67	点検中	点検中	58	69	52	66
15:50	65	点検中	点検中	58	70	52	65
16:00	66	点検中	点検中	58	70	52	66
16:10	67	点検中	点検中	62	71	56	69
16:20	69	点検中	点検中	64	74	57	69
16:30	69	点検中	点検中	64	74	58	69
16:40	69	点検中	点検中	63	75	57	69
16:50	69	点検中	点検中	63	75	57	69
17:00	68	点検中	点検中	62	74	55	68
17:10	68	点検中	点検中	60	73	55	67
17:20	67	点検中	点検中	60	72	54	68
17:30	67	点検中	点検中	60	71	54	67
17:40	68	点検中	点検中	60	71	54	67
17:50	67	点検中	点検中	59	70	53	67
18:00	66	点検中	点検中	59	70	53	66
18:10	67	点検中	点検中	60	70	53	66
18:20	67	点検中	点検中	58	69	52	66
18:30	67	点検中	点検中	58	70	53	66
18:40	67	点検中	点検中	58	69	52	67
18:50	67	点検中	点検中	59	70	52	65
19:00	66	点検中	点検中	57	71	52	66
19:10	67	点検中	点検中	57	70	52	66
19:20	67	点検中	点検中	57	70	52	67
19:30	66	点検中	点検中	58	70	52	66
19:40	67	点検中	点検中	58	70	52	66
19:50	66	点検中	点検中	57	70	53	66
20:00	67	点検中	点検中	57	70	53	66
20:10	67	点検中	点検中	58	69	52	67
20:20	66	点検中	点検中	58	70	52	66
20:30	66	点検中	点検中	57	69	53	66
20:40	66	点検中	点検中	57	70	52	65
20:50	65	点検中	点検中	57	69	53	66
21:00	65	点検中	点検中	58	69	52	66
21:10	66	点検中	点検中	57	68	52	66
21:20	67	点検中	点検中	57	68	52	65
21:30	67	点検中	点検中	57	68	52	66
21:40	66	点検中	点検中	57	68	52	66
21:50	67	点検中	点検中	58	69	52	66
22:00	67	点検中	点検中	57	68	52	66
22:10	67	点検中	点検中	58	68	52	66
22:20	67	点検中	点検中	58	68	52	67
22:30	67	点検中	点検中	58	68	52	66
22:40	67	点検中	点検中	57	68	52	66
22:50	67	点検中	点検中	58	68	53	66
23:00	67	点検中	点検中	57	68	53	66
23:10	67	点検中	点検中	58	68	53	67
23:20	67	点検中	点検中	58	68	52	66
23:30	67	点検中	点検中	58	69	52	66
23:40	68	点検中	点検中	58	68	53	66
23:50	68	点検中	点検中	58	68	53	66
0:00	68	点検中	点検中	58	68	53	66