

茨城県の放射線量の状況について(3月13日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	46	72	48	49	40	47	点検中
0:20	54	45	72	49	48	40	47	点検中
0:30	53	46	71	48	48	40	47	点検中
0:40	53	46	72	48	48	40	47	点検中
0:50	53	46	72	48	48	40	46	点検中
1:00	53	46	72	48	49	40	46	点検中
1:10	53	47	72	47	49	40	46	点検中
1:20	53	47	72	48	49	40	46	点検中
1:30	54	46	72	48	50	40	46	点検中
1:40	53	47	71	48	49	40	46	点検中
1:50	53	46	72	49	49	41	46	点検中
2:00	53	47	72	48	48	40	46	点検中
2:10	54	46	71	49	49	40	46	点検中
2:20	53	46	71	48	49	40	46	点検中
2:30	53	46	72	48	49	40	47	点検中
2:40	53	46	71	48	49	40	46	点検中
2:50	53	47	71	49	49	40	46	点検中
3:00	53	47	71	48	49	40	46	点検中
3:10	54	47	71	49	49	41	46	点検中
3:20	54	47	71	49	49	41	47	点検中
3:30	54	46	71	49	49	40	46	点検中
3:40	54	47	72	49	49	41	47	点検中
3:50	54	47	71	48	49	40	46	点検中
4:00	54	47	72	49	49	41	47	点検中
4:10	54	47	72	48	49	40	47	点検中
4:20	54	46	71	48	50	41	47	点検中
4:30	53	46	72	48	49	40	47	点検中
4:40	53	46	72	48	49	40	47	点検中
4:50	54	46	72	48	50	41	47	点検中
5:00	54	47	72	49	49	40	47	点検中
5:10	53	47	72	48	49	41	47	点検中
5:20	54	46	72	49	50	40	47	点検中
5:30	53	47	72	49	50	40	47	点検中
5:40	54	47	72	49	49	40	46	点検中
5:50	53	47	71	49	50	40	47	点検中
6:00	53	47	72	49	49	40	46	点検中
6:10	53	47	72	49	49	40	47	点検中
6:20	53	47	72	49	49	40	47	点検中
6:30	54	47	72	49	49	40	47	点検中
6:40	54	47	72	49	49	41	47	点検中
6:50	54	47	72	49	50	40	47	点検中
7:00	53	47	72	49	50	40	47	点検中
7:10	54	48	72	49	50	40	46	点検中
7:20	53	48	72	49	49	40	47	点検中
7:30	54	47	72	49	49	41	46	点検中
7:40	54	48	72	49	50	40	48	点検中
7:50	54	47	72	48	49	41	47	点検中
8:00	54	47	73	48	49	41	47	点検中
8:10	54	47	72	49	50	41	47	点検中
8:20	54	47	72	49	49	41	47	点検中
8:30	53	46	72	49	49	40	47	点検中
8:40	53	46	72	49	50	41	47	点検中
8:50	53	46	71	49	48	40	46	点検中
9:00	52	46	71	48	49	40	46	点検中
9:10	53	46	72	49	49	40	46	点検中
9:20	53	46	71	47	49	40	46	点検中
9:30	52	46	72	49	49	40	46	点検中
9:40	53	46	71	48	48	40	46	点検中
9:50	53	46	72	48	48	40	46	点検中
10:00	53	45	72	48	48	40	46	点検中
10:10	53	46	72	49	48	40	46	点検中
10:20	53	45	72	48	48	40	46	点検中
10:30	53	46	72	48	48	41	46	点検中
10:40	52	45	72	48	49	40	46	点検中
10:50	52	46	72	点検中	49	40	46	点検中
11:00	53	45	71	点検中	48	40	46	点検中
11:10	53	46	71	49	48	39	46	点検中
11:20	53	46	72	47	48	40	46	点検中
11:30	53	46	72	48	48	40	46	点検中
11:40	52	46	72	48	48	40	46	点検中
11:50	53	46	71	48	49	40	46	点検中
12:00	53	46	71	48	48	40	47	点検中

茨城県の放射線量の状況について(3月13日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	46	72	48	48	40	47	点検中
12:20	53	45	72	48	48	41	46	点検中
12:30	53	46	72	48	49	40	46	点検中
12:40	53	46	72	48	48	40	47	点検中
12:50	53	46	72	48	49	40	46	点検中
13:00	53	46	72	48	48	41	46	点検中
13:10	53	46	72	48	48	40	46	点検中
13:20	53	46	72	48	49	41	46	点検中
13:30	53	46	72	48	49	40	点検中	点検中
13:40	54	46	72	48	49	40	点検中	点検中
13:50	53	46	71	47	48	40	点検中	点検中
14:00	53	46	71	48	48	40	46	点検中
14:10	53	46	71	49	49	40	46	点検中
14:20	53	46	72	48	48	40	46	点検中
14:30	52	46	72	48	48	40	47	点検中
14:40	52	45	71	48	48	40	46	点検中
14:50	53	45	72	48	48	41	46	点検中
15:00	52	46	72	47	49	40	46	点検中
15:10	53	45	71	48	48	40	46	点検中
15:20	53	45	72	48	48	40	46	点検中
15:30	53	46	73	48	49	40	47	点検中
15:40	53	45	71	48	49	40	47	点検中
15:50	53	46	71	48	49	40	46	点検中
16:00	53	45	71	48	48	40	46	点検中
16:10	53	45	71	48	48	40	46	点検中
16:20	53	46	72	47	48	40	46	点検中
16:30	53	45	71	48	49	40	46	点検中
16:40	52	46	72	48	48	40	46	点検中
16:50	53	45	72	48	48	40	46	点検中
17:00	52	45	72	48	49	40	46	点検中
17:10	52	45	72	48	48	40	46	点検中
17:20	52	46	72	48	49	40	46	点検中
17:30	53	46	71	47	48	40	46	点検中
17:40	53	45	71	48	48	40	45	点検中
17:50	52	45	71	48	48	40	46	点検中
18:00	53	46	71	48	48	40	46	点検中
18:10	52	46	72	48	48	39	46	点検中
18:20	53	45	72	48	48	40	46	点検中
18:30	53	46	72	48	48	40	46	点検中
18:40	52	45	71	48	49	40	46	点検中
18:50	52	45	71	48	48	39	46	点検中
19:00	53	45	71	48	48	41	47	点検中
19:10	52	45	71	48	49	40	46	点検中
19:20	53	46	71	48	48	39	46	点検中
19:30	53	46	72	47	48	39	46	点検中
19:40	52	45	72	48	48	39	46	点検中
19:50	53	45	71	48	49	39	46	点検中
20:00	53	45	71	48	48	39	46	点検中
20:10	53	46	72	49	48	40	46	点検中
20:20	53	46	71	47	49	40	47	点検中
20:30	53	46	71	49	48	40	46	点検中
20:40	53	47	71	47	49	40	46	点検中
20:50	53	46	72	48	48	40	47	点検中
21:00	53	46	72	48	48	40	46	点検中
21:10	53	46	73	48	48	40	46	点検中
21:20	53	46	71	48	49	40	46	点検中
21:30	53	46	72	48	49	40	47	点検中
21:40	53	46	72	49	49	40	47	点検中
21:50	54	46	71	48	49	40	47	点検中
22:00	53	46	71	48	49	40	47	点検中
22:10	53	46	72	49	49	39	46	点検中
22:20	54	47	72	48	49	40	47	点検中
22:30	52	47	72	49	49	40	47	点検中
22:40	53	47	72	49	50	40	47	点検中
22:50	54	46	72	49	49	40	47	点検中
23:00	53	47	72	49	49	40	47	点検中
23:10	53	47	71	49	50	41	47	点検中
23:20	53	46	72	49	49	41	47	点検中
23:30	54	46	72	48	49	40	47	点検中
23:40	54	47	73	48	49	41	47	点検中
23:50	54	47	72	48	49	41	47	点検中
0:00	54	47	72	49	49	41	47	点検中

茨城県の放射線量の状況について(3月14日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	54	47	72	49	49	41	47	点検中
0:20	54	47	72	49	49	41	47	点検中
0:30	54	46	72	49	49	41	47	点検中
0:40	53	47	72	49	50	41	47	点検中
0:50	54	47	73	49	50	41	47	点検中
1:00	54	47	72	49	50	40	48	点検中
1:10	54	46	72	50	49	41	48	点検中
1:20	54	46	72	49	49	41	47	点検中
1:30	54	47	71	49	49	41	47	点検中
1:40	54	46	72	49	49	41	47	点検中
1:50	54	46	72	49	50	41	47	点検中
2:00	54	46	73	49	49	40	48	点検中
2:10	54	46	72	49	49	41	47	点検中
2:20	54	46	72	49	49	41	47	点検中
2:30	54	46	72	49	49	41	47	点検中
2:40	54	46	72	49	49	41	47	点検中
2:50	53	47	72	49	49	40	47	点検中
3:00	54	46	72	49	49	40	46	点検中
3:10	54	47	71	49	49	40	47	点検中
3:20	54	46	71	49	49	40	47	点検中
3:30	54	46	73	49	49	40	47	点検中
3:40	53	47	72	48	49	40	47	点検中
3:50	53	46	72	49	49	40	47	点検中
4:00	54	47	70	49	48	40	47	点検中
4:10	53	46	71	49	50	41	47	点検中
4:20	54	46	72	49	49	40	47	点検中
4:30	53	47	71	49	49	40	47	点検中
4:40	54	46	73	48	49	41	48	点検中
4:50	53	47	73	48	49	41	47	点検中
5:00	54	46	72	49	50	41	47	点検中
5:10	54	46	72	49	49	41	47	点検中
5:20	53	47	73	49	49	40	48	点検中
5:30	54	46	72	48	48	41	47	点検中
5:40	53	46	72	48	49	42	47	点検中
5:50	54	47	72	49	49	41	47	点検中
6:00	54	47	72	48	49	41	47	点検中
6:10	53	47	72	49	50	41	48	点検中
6:20	54	46	72	49	50	41	47	点検中
6:30	54	46	72	49	50	41	47	点検中
6:40	54	47	72	49	49	41	47	点検中
6:50	54	47	72	48	49	40	47	点検中
7:00	54	47	72	49	50	41	47	点検中
7:10	54	47	71	49	49	42	48	点検中
7:20	54	46	72	49	50	41	47	点検中
7:30	54	47	71	49	49	41	48	点検中
7:40	54	47	72	49	49	41	48	点検中
7:50	54	47	72	49	49	41	47	点検中
8:00	53	47	72	49	49	41	48	点検中
8:10	54	47	73	50	49	42	47	点検中
8:20	54	47	72	48	50	42	47	点検中
8:30	54	47	72	48	49	41	47	点検中
8:40	54	46	72	49	49	41	47	点検中
8:50	54	47	72	48	49	41	48	点検中
9:00	54	46	72	48	49	41	48	点検中
9:10	53	46	72	49	49	41	47	点検中
9:20	54	46	72	49	48	41	47	点検中
9:30	53	45	72	48	49	41	47	点検中
9:40	54	46	73	48	49	40	47	点検中
9:50	53	46	72	49	49	40	47	点検中
10:00	53	46	72	48	48	40	47	点検中
10:10	53	46	72	49	49	40	47	点検中
10:20	53	45	72	47	49	40	46	点検中
10:30	52	47	71	49	49	40	46	点検中
10:40	53	46	72	48	48	41	47	点検中
10:50	53	46	71	47	49	41	47	点検中
11:00	52	46	71	48	49	40	46	点検中
11:10	51	46	72	48	48	40	46	点検中
11:20	50	46	72	48	48	40	46	点検中
11:30	51	46	71	47	49	41	46	点検中
11:40	50	46	71	49	48	40	46	点検中
11:50	51	45	72	48	48	40	46	点検中
12:00	52	46	72	48	48	39	47	点検中

茨城県の放射線量の状況について(3月14日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	52	46	72	48	48	40	46	点検中
12:20	52	46	71	49	48	40	45	点検中
12:30	52	46	71	48	48	40	46	点検中
12:40	52	45	72	47	48	40	46	点検中
12:50	51	45	72	48	48	40	47	点検中
13:00	52	46	71	48	48	39	46	点検中
13:10	52	45	72	48	48	40	47	点検中
13:20	53	46	72	48	49	40	46	点検中
13:30	53	46	72	48	48	40	46	点検中
13:40	53	46	72	48	48	40	47	点検中
13:50	53	45	71	48	49	39	47	点検中
14:00	52	46	71	48	48	40	47	点検中
14:10	53	46	72	48	48	40	46	点検中
14:20	53	46	72	48	48	40	46	点検中
14:30	53	46	71	48	48	40	47	点検中
14:40	53	46	72	48	48	40	46	点検中
14:50	52	46	71	48	48	40	46	点検中
15:00	53	46	71	48	49	40	46	点検中
15:10	52	45	72	48	48	40	46	点検中
15:20	53	45	71	48	49	40	46	点検中
15:30	52	46	71	48	48	40	47	点検中
15:40	53	46	72	48	48	40	47	点検中
15:50	53	46	72	48	49	40	46	点検中
16:00	53	46	71	48	48	40	46	点検中
16:10	53	46	72	48	48	40	46	点検中
16:20	53	46	72	48	48	40	46	点検中
16:30	53	45	71	48	48	40	46	点検中
16:40	52	46	71	48	49	40	47	点検中
16:50	52	45	72	47	49	39	46	点検中
17:00	53	46	72	49	49	39	47	点検中
17:10	53	46	72	48	49	40	46	点検中
17:20	53	46	72	48	48	39	47	点検中
17:30	53	45	72	49	48	38	47	点検中
17:40	53	46	71	48	49	39	46	点検中
17:50	53	46	71	48	48	40	46	点検中
18:00	53	45	72	49	49	40	46	点検中
18:10	53	46	72	49	48	40	46	点検中
18:20	53	46	71	48	48	39	46	点検中
18:30	52	46	72	48	49	40	46	点検中
18:40	54	45	70	48	48	40	46	点検中
18:50	52	46	71	48	48	40	46	点検中
19:00	53	46	71	48	48	40	47	点検中
19:10	53	45	71	48	49	40	46	点検中
19:20	53	46	71	48	48	39	46	点検中
19:30	53	46	71	48	48	40	46	点検中
19:40	52	46	72	47	49	40	46	点検中
19:50	53	46	71	49	49	39	46	点検中
20:00	52	46	71	48	48	39	46	点検中
20:10	53	45	72	47	49	40	46	点検中
20:20	52	46	71	48	48	40	46	点検中
20:30	53	45	72	48	48	40	46	点検中
20:40	53	46	72	48	48	40	46	点検中
20:50	53	45	71	48	48	40	46	点検中
21:00	53	46	72	48	48	40	46	点検中
21:10	53	46	72	48	48	40	46	点検中
21:20	53	46	72	48	48	40	46	点検中
21:30	53	46	72	48	48	40	47	点検中
21:40	53	46	71	49	49	40	47	点検中
21:50	53	46	72	49	48	40	47	点検中
22:00	53	46	71	48	49	40	47	点検中
22:10	54	46	72	48	48	40	47	点検中
22:20	53	46	72	49	49	40	46	点検中
22:30	54	46	72	49	49	40	47	点検中
22:40	53	46	73	48	49	40	46	点検中
22:50	53	46	71	48	48	40	46	点検中
23:00	53	46	72	48	49	40	47	点検中
23:10	53	46	72	48	50	40	47	点検中
23:20	53	46	72	48	49	41	47	点検中
23:30	53	47	73	49	49	41	47	点検中
23:40	53	46	72	49	49	40	47	点検中
23:50	53	46	72	48	48	40	47	点検中
0:00	54	46	72	49	49	40	47	点検中

茨城県の放射線量の状況について(3月15日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	54	47	72	49	50	41	47	点検中
0:20	53	46	71	48	49	40	47	点検中
0:30	53	46	72	48	49	40	46	点検中
0:40	54	46	71	48	49	40	47	点検中
0:50	54	46	72	49	49	41	47	点検中
1:00	53	46	72	48	49	41	47	点検中
1:10	54	47	71	49	49	40	47	点検中
1:20	53	47	71	49	49	40	47	点検中
1:30	55	47	72	49	49	40	47	点検中
1:40	54	46	72	48	49	40	47	点検中
1:50	54	46	73	48	49	41	47	点検中
2:00	53	47	72	48	49	41	47	点検中
2:10	54	46	72	49	50	41	47	点検中
2:20	54	46	72	49	49	40	47	点検中
2:30	54	47	72	49	50	41	47	点検中
2:40	54	47	71	49	50	40	47	点検中
2:50	54	47	72	49	50	41	47	点検中
3:00	55	46	72	49	49	41	46	点検中
3:10	54	47	72	49	50	40	48	点検中
3:20	53	46	73	49	50	41	47	点検中
3:30	54	47	72	49	49	40	47	点検中
3:40	54	46	72	49	49	41	47	点検中
3:50	53	47	72	49	50	41	47	点検中
4:00	54	46	72	49	49	41	47	点検中
4:10	54	47	72	49	49	41	47	点検中
4:20	54	47	73	49	49	41	47	点検中
4:30	54	46	72	49	49	41	47	点検中
4:40	53	47	72	49	49	41	47	点検中
4:50	54	46	73	49	50	40	47	点検中
5:00	54	47	71	49	49	41	47	点検中
5:10	54	47	71	49	49	41	47	点検中
5:20	54	48	72	49	50	41	47	点検中
5:30	54	47	72	50	50	40	48	点検中
5:40	54	46	72	49	49	41	48	点検中
5:50	54	46	73	49	50	41	47	点検中
6:00	54	47	72	49	49	41	47	点検中
6:10	54	47	72	49	50	41	48	点検中
6:20	54	47	73	49	50	40	48	点検中
6:30	54	47	72	49	50	41	48	点検中
6:40	54	47	73	49	49	41	48	点検中
6:50	53	47	73	49	49	41	47	点検中
7:00	55	47	71	49	49	40	47	点検中
7:10	54	47	72	50	49	40	47	点検中
7:20	54	47	73	49	50	41	48	点検中
7:30	54	47	72	49	50	41	48	点検中
7:40	54	47	72	49	50	41	47	点検中
7:50	54	47	73	49	49	41	47	点検中
8:00	54	46	72	50	49	41	47	点検中
8:10	54	47	72	49	49	41	47	点検中
8:20	54	47	73	49	49	41	48	点検中
8:30	54	47	72	49	50	41	47	点検中
8:40	53	47	72	49	50	41	46	点検中
8:50	53	46	73	49	49	40	46	点検中
9:00	53	46	71	49	49	41	48	点検中
9:10	53	47	72	50	49	41	47	点検中
9:20	54	46	72	49	49	40	47	点検中
9:30	54	46	72	49	49	40	47	点検中
9:40	54	46	72	49	49	40	47	点検中
9:50	54	46	72	48	50	40	46	点検中
10:00	53	46	72	49	49	40	47	点検中
10:10	54	46	72	49	49	40	47	点検中
10:20	53	46	72	48	48	40	46	点検中
10:30	53	46	72	48	48	40	47	点検中
10:40	53	46	72	48	49	41	46	点検中
10:50	53	46	72	48	48	40	47	点検中
11:00	53	46	72	48	48	40	46	点検中
11:10	53	46	73	48	48	40	46	点検中
11:20	53	46	72	49	49	39	46	点検中
11:30	53	46	72	49	49	40	46	点検中
11:40	53	46	73	48	49	40	46	点検中
11:50	53	46	72	48	48	40	47	点検中
12:00	53	46	72	48	48	40	46	点検中

茨城県の放射線量の状況について(3月15日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	45	71	47	48	40	46	点検中
12:20	53	46	71	48	48	39	46	点検中
12:30	52	46	72	48	49	40	46	点検中
12:40	53	45	72	48	48	40	45	点検中
12:50	53	45	71	47	48	40	46	点検中
13:00	53	46	71	48	48	40	47	点検中
13:10	53	46	72	48	49	40	46	点検中
13:20	52	45	72	48	49	40	46	点検中
13:30	53	46	71	49	49	40	46	点検中
13:40	52	45	72	47	48	40	45	点検中
13:50	53	46	71	48	48	40	45	点検中
14:00	53	46	71	48	48	40	46	点検中
14:10	52	45	71	48	48	40	46	点検中
14:20	53	46	72	48	48	39	46	点検中
14:30	52	45	72	48	48	40	47	点検中
14:40	53	46	71	48	48	40	46	点検中
14:50	52	46	71	48	48	39	47	点検中
15:00	53	46	71	48	48	39	45	点検中
15:10	52	46	71	48	48	40	46	点検中
15:20	53	46	71	48	48	39	46	点検中
15:30	53	45	72	47	48	40	46	点検中
15:40	53	46	71	48	48	40	46	点検中
15:50	52	45	72	47	48	40	47	点検中
16:00	53	45	71	47	47	40	46	点検中
16:10	53	45	71	48	48	40	46	点検中
16:20	53	45	71	47	48	39	46	点検中
16:30	53	45	71	48	48	40	47	点検中
16:40	53	45	71	48	49	40	46	点検中
16:50	53	45	71	48	48	40	46	点検中
17:00	53	46	71	49	49	39	46	点検中
17:10	53	46	71	48	48	39	46	点検中
17:20	53	45	71	48	48	40	46	点検中
17:30	53	46	71	47	47	40	46	点検中
17:40	53	45	71	47	48	39	46	点検中
17:50	52	45	71	48	48	40	45	点検中
18:00	53	45	72	48	48	39	45	点検中
18:10	53	46	71	48	49	40	46	点検中
18:20	53	45	71	48	48	40	47	点検中
18:30	53	45	71	48	48	40	46	点検中
18:40	53	45	71	48	48	39	46	点検中
18:50	53	45	72	49	48	40	46	点検中
19:00	52	45	71	48	48	39	47	点検中
19:10	53	46	71	49	48	40	46	点検中
19:20	52	46	72	48	48	40	46	点検中
19:30	53	46	71	48	48	40	46	点検中
19:40	53	45	72	48	48	40	46	点検中
19:50	53	46	72	48	49	40	46	点検中
20:00	53	45	71	48	48	40	46	点検中
20:10	53	46	72	49	49	40	46	点検中
20:20	53	46	72	48	49	39	47	点検中
20:30	53	46	72	48	48	39	46	点検中
20:40	53	47	72	48	49	39	46	点検中
20:50	53	46	71	48	48	40	47	点検中
21:00	53	46	72	48	49	40	47	点検中
21:10	54	46	72	49	49	40	47	点検中
21:20	54	47	71	48	49	40	47	点検中
21:30	53	46	72	49	48	40	47	点検中
21:40	53	46	72	49	49	40	46	点検中
21:50	53	46	72	48	48	40	46	点検中
22:00	52	47	72	48	48	41	46	点検中
22:10	54	46	72	48	49	40	47	点検中
22:20	53	46	72	49	49	40	47	点検中
22:30	55	46	72	49	49	40	47	点検中
22:40	53	46	72	48	49	40	47	点検中
22:50	54	47	71	49	49	41	47	点検中
23:00	53	47	71	48	49	40	47	点検中
23:10	53	46	72	49	49	41	47	点検中
23:20	54	46	72	48	49	41	47	点検中
23:30	53	46	72	48	49	41	47	点検中
23:40	53	47	72	49	49	40	47	点検中
23:50	53	46	71	49	49	41	47	点検中
0:00	54	46	71	48	49	41	47	点検中

茨城県の放射線量の状況について(3月16日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	46	72	49	50	41	46	点検中
0:20	53	46	72	49	49	40	46	点検中
0:30	53	46	73	49	49	41	47	点検中
0:40	54	46	72	49	49	40	47	点検中
0:50	54	47	71	49	49	40	47	点検中
1:00	54	47	72	48	49	41	47	点検中
1:10	54	47	72	49	49	40	47	点検中
1:20	53	46	71	50	49	40	47	点検中
1:30	53	46	72	48	49	41	46	点検中
1:40	53	46	72	49	49	41	47	点検中
1:50	54	47	72	50	49	41	46	点検中
2:00	54	46	72	50	49	40	46	点検中
2:10	54	46	72	49	49	41	46	点検中
2:20	53	47	72	49	49	41	47	点検中
2:30	54	46	72	49	50	41	47	点検中
2:40	54	46	72	49	50	41	47	点検中
2:50	54	47	72	49	49	40	47	点検中
3:00	54	47	72	48	49	40	47	点検中
3:10	54	47	72	50	49	41	48	点検中
3:20	54	47	73	49	50	40	47	点検中
3:30	54	47	72	49	49	40	47	点検中
3:40	54	46	72	49	50	40	47	点検中
3:50	54	47	72	49	49	41	47	点検中
4:00	54	47	73	49	49	41	48	点検中
4:10	54	47	72	48	50	41	48	点検中
4:20	54	47	72	49	49	41	48	点検中
4:30	54	47	72	49	50	41	47	点検中
4:40	54	47	72	49	48	42	47	点検中
4:50	54	47	73	49	50	41	47	点検中
5:00	54	47	73	49	49	40	47	点検中
5:10	53	47	72	49	49	41	48	点検中
5:20	54	47	72	49	49	42	47	点検中
5:30	54	46	72	49	50	41	47	点検中
5:40	54	47	72	49	49	41	47	点検中
5:50	54	47	72	50	49	41	47	点検中
6:00	54	47	72	50	49	41	47	点検中
6:10	55	48	72	49	49	41	47	点検中
6:20	53	47	72	49	50	41	47	点検中
6:30	54	47	72	49	49	41	47	点検中
6:40	55	47	73	49	49	41	48	点検中
6:50	54	47	72	49	49	41	48	点検中
7:00	54	47	72	50	50	41	48	点検中
7:10	54	47	73	49	49	41	47	点検中
7:20	54	47	73	49	49	41	48	点検中
7:30	54	47	72	49	50	41	47	点検中
7:40	54	48	72	49	50	41	48	点検中
7:50	55	47	73	50	50	41	47	点検中
8:00	55	47	72	50	50	41	47	点検中
8:10	54	48	72	50	50	42	48	点検中
8:20	54	48	73	50	49	41	48	点検中
8:30	55	48	72	50	50	41	48	点検中
8:40	53	47	72	49	50	41	49	点検中
8:50	54	47	72	49	50	41	47	点検中
9:00	53	47	72	48	50	42	47	点検中
9:10	53	47	73	49	49	41	48	点検中
9:20	54	47	73	50	49	41	47	点検中
9:30	54	47	72	49	50	41	47	点検中
9:40	54	47	72	49	49	41	47	点検中
9:50	54	48	72	49	50	41	47	点検中
10:00	53	47	72	49	49	41	47	点検中
10:10	54	47	72	49	49	41	47	点検中
10:20	54	46	72	50	49	41	47	点検中
10:30	54	47	72	48	49	41	47	点検中
10:40	53	46	72	49	49	40	47	点検中
10:50	54	46	72	49	49	41	47	点検中
11:00	53	46	71	49	48	40	47	点検中
11:10	53	47	73	48	48	40	47	点検中
11:20	53	46	71	49	49	40	46	点検中
11:30	53	46	72	48	50	40	46	点検中
11:40	53	46	72	49	49	40	46	点検中
11:50	53	46	72	48	49	40	46	点検中
12:00	53	46	71	49	49	40	47	点検中

茨城県の放射線量の状況について(3月16日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	46	72	49	48	41	46	点検中
12:20	53	47	72	50	48	41	46	点検中
12:30	53	46	72	48	48	40	46	点検中
12:40	54	46	72	49	49	40	47	点検中
12:50	54	46	71	49	49	40	47	点検中
13:00	53	46	71	49	49	40	46	点検中
13:10	53	46	71	48	48	40	47	点検中
13:20	52	46	72	48	48	40	46	点検中
13:30	53	46	71	49	48	41	46	点検中
13:40	52	46	72	48	48	40	47	点検中
13:50	53	46	72	49	49	40	46	点検中
14:00	53	45	72	48	48	40	46	点検中
14:10	53	45	71	48	48	40	46	点検中
14:20	53	46	71	48	48	40	46	点検中
14:30	52	46	72	48	48	40	46	点検中
14:40	52	46	71	48	48	40	46	点検中
14:50	52	45	72	48	48	39	46	点検中
15:00	52	45	72	48	48	41	46	点検中
15:10	52	45	72	48	49	40	46	点検中
15:20	53	45	72	48	48	40	46	点検中
15:30	53	46	72	48	48	40	47	点検中
15:40	53	46	71	47	49	40	45	点検中
15:50	53	46	71	48	48	40	46	点検中
16:00	53	46	72	49	48	40	47	点検中
16:10	53	45	71	47	48	40	46	点検中
16:20	52	45	71	48	49	40	46	点検中
16:30	53	46	71	48	48	39	46	点検中
16:40	52	45	71	48	49	40	46	点検中
16:50	52	45	72	48	48	40	46	点検中
17:00	52	45	71	48	48	40	46	点検中
17:10	52	46	71	48	48	39	46	点検中
17:20	53	46	72	48	48	40	46	点検中
17:30	52	46	72	48	48	40	46	点検中
17:40	53	46	71	47	48	40	46	点検中
17:50	53	45	72	48	48	39	46	点検中
18:00	52	45	72	48	48	39	46	点検中
18:10	53	45	71	47	48	40	46	点検中
18:20	53	45	72	47	48	39	47	点検中
18:30	53	46	72	48	48	40	46	点検中
18:40	53	46	71	48	48	40	46	点検中
18:50	53	46	71	48	48	40	46	点検中
19:00	52	46	71	48	48	40	47	点検中
19:10	53	45	72	49	49	40	46	点検中
19:20	53	46	71	48	48	40	45	点検中
19:30	53	46	72	48	48	40	46	点検中
19:40	53	45	71	48	48	40	46	点検中
19:50	53	46	71	47	48	40	47	点検中
20:00	53	46	71	48	48	40	46	点検中
20:10	52	46	72	47	48	40	46	点検中
20:20	53	46	71	48	48	39	47	点検中
20:30	53	46	72	47	48	41	46	点検中
20:40	53	46	71	48	48	40	47	点検中
20:50	53	46	71	48	48	39	46	点検中
21:00	53	46	71	48	48	39	46	点検中
21:10	53	46	71	48	48	40	47	点検中
21:20	53	46	71	48	49	39	46	点検中
21:30	53	45	71	48	48	40	46	点検中
21:40	53	46	72	48	49	40	46	点検中
21:50	53	46	72	48	48	40	47	点検中
22:00	53	46	72	48	48	40	46	点検中
22:10	53	46	72	48	48	41	46	点検中
22:20	53	46	71	48	49	40	46	点検中
22:30	53	46	71	48	49	40	47	点検中
22:40	53	46	72	48	49	40	46	点検中
22:50	53	46	72	48	49	40	47	点検中
23:00	53	46	71	47	48	40	46	点検中
23:10	54	46	71	48	49	40	47	点検中
23:20	53	46	72	48	49	41	47	点検中
23:30	53	46	71	48	49	40	47	点検中
23:40	53	47	71	48	49	40	46	点検中
23:50	54	46	71	48	49	41	46	点検中
0:00	54	45	72	49	49	40	47	点検中

茨城県の放射線量の状況について(3月17日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	47	72	48	49	41	47	点検中
0:20	54	46	72	48	49	40	47	点検中
0:30	53	47	72	48	49	40	47	点検中
0:40	54	46	72	49	49	41	47	点検中
0:50	53	47	72	48	49	41	47	点検中
1:00	53	46	72	48	49	40	47	点検中
1:10	54	47	72	48	49	40	47	点検中
1:20	53	46	72	49	49	40	47	点検中
1:30	54	46	72	48	49	40	47	点検中
1:40	54	46	71	49	48	41	47	点検中
1:50	53	46	72	48	49	40	47	点検中
2:00	54	46	72	48	49	41	46	点検中
2:10	54	46	72	49	49	40	46	点検中
2:20	54	46	71	49	49	40	47	点検中
2:30	53	46	72	49	49	40	46	点検中
2:40	53	46	72	49	48	39	47	点検中
2:50	53	46	71	49	50	39	47	点検中
3:00	53	46	72	49	49	40	47	点検中
3:10	53	46	71	49	49	39	47	点検中
3:20	54	45	72	48	49	40	47	点検中
3:30	53	45	72	49	48	40	47	点検中
3:40	54	46	71	48	49	40	46	点検中
3:50	53	45	72	49	49	39	47	点検中
4:00	54	46	71	48	49	40	47	点検中
4:10	53	46	72	49	49	40	47	点検中
4:20	53	46	72	48	49	39	47	点検中
4:30	54	46	72	48	49	40	46	点検中
4:40	53	46	72	48	49	40	46	点検中
4:50	54	46	72	49	49	39	46	点検中
5:00	54	46	72	48	49	40	47	点検中
5:10	54	46	72	48	49	40	47	点検中
5:20	53	46	72	48	49	40	46	点検中
5:30	53	46	72	49	49	40	46	点検中
5:40	54	47	72	49	49	40	47	点検中
5:50	53	46	72	49	49	40	47	点検中
6:00	53	46	71	48	49	40	47	点検中
6:10	53	46	71	49	49	41	47	点検中
6:20	53	46	72	48	49	40	47	点検中
6:30	53	46	72	48	48	40	47	点検中
6:40	54	46	72	49	49	40	46	点検中
6:50	53	47	71	48	49	40	46	点検中
7:00	53	46	72	49	48	40	46	点検中
7:10	54	46	72	49	49	40	46	点検中
7:20	54	47	72	49	49	40	47	点検中
7:30	54	46	72	48	48	40	46	点検中
7:40	53	46	71	48	49	40	47	点検中
7:50	54	46	72	48	48	40	47	点検中
8:00	53	46	72	49	48	40	46	点検中
8:10	53	46	71	48	48	40	46	点検中
8:20	53	46	72	49	49	40	47	点検中
8:30	53	45	72	48	49	40	46	点検中
8:40	53	46	72	49	48	40	47	点検中
8:50	52	46	71	48	48	40	46	点検中
9:00	52	46	71	49	49	40	46	点検中
9:10	53	46	72	48	48	40	46	点検中
9:20	53	46	71	48	48	40	46	点検中
9:30	52	46	72	47	48	40	47	点検中
9:40	52	46	72	48	49	40	47	点検中
9:50	53	46	71	48	48	40	46	点検中
10:00	53	45	71	48	48	40	46	点検中
10:10	52	46	71	48	49	41	47	点検中
10:20	52	46	72	47	49	40	46	点検中
10:30	52	46	72	48	48	40	47	点検中
10:40	52	45	72	48	48	41	46	点検中
10:50	52	45	72	48	48	40	46	点検中
11:00	53	46	72	47	48	40	46	点検中
11:10	53	46	72	48	48	40	47	点検中
11:20	52	45	72	47	48	40	47	点検中
11:30	53	45	72	48	48	40	46	点検中
11:40	53	46	72	47	48	39	46	点検中
11:50	53	45	71	47	48	40	46	点検中
12:00	51	45	72	47	48	40	47	点検中

茨城県の放射線量の状況について(3月17日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	46	72	48	48	39	46	点検中
12:20	52	46	72	47	49	40	46	点検中
12:30	52	45	72	48	48	40	46	点検中
12:40	52	46	71	47	48	40	46	点検中
12:50	53	46	71	48	48	40	46	点検中
13:00	52	46	71	48	48	39	46	点検中
13:10	53	45	71	48	48	40	47	点検中
13:20	52	45	72	48	48	40	46	点検中
13:30	52	45	72	47	48	40	45	点検中
13:40	53	45	72	47	48	40	46	点検中
13:50	52	46	72	47	47	40	46	点検中
14:00	53	45	71	48	48	40	46	点検中
14:10	53	45	71	48	48	40	46	点検中
14:20	52	45	70	48	48	40	46	点検中
14:30	51	45	72	48	49	40	46	点検中
14:40	51	46	72	48	48	40	46	点検中
14:50	52	46	71	47	48	40	46	点検中
15:00	52	46	71	48	48	40	46	点検中
15:10	51	45	71	47	47	39	46	点検中
15:20	52	45	71	47	48	40	47	点検中
15:30	53	46	72	48	48	40	46	点検中
15:40	52	45	71	48	48	39	46	点検中
15:50	52	45	70	48	48	40	46	点検中
16:00	52	45	70	47	48	40	46	点検中
16:10	52	45	72	48	47	40	46	点検中
16:20	52	45	71	47	47	39	46	点検中
16:30	52	45	71	47	48	39	45	点検中
16:40	52	45	71	47	48	39	46	点検中
16:50	51	46	72	47	47	40	46	点検中
17:00	52	45	71	47	47	40	46	点検中
17:10	51	45	71	48	48	39	46	点検中
17:20	52	45	71	48	47	40	46	点検中
17:30	52	45	71	47	48	40	46	点検中
17:40	52	45	71	47	48	40	46	点検中
17:50	53	45	72	48	48	39	46	点検中
18:00	53	45	71	47	47	40	46	点検中
18:10	52	45	71	48	48	39	46	点検中
18:20	53	45	71	47	48	40	46	点検中
18:30	52	46	71	47	48	39	46	点検中
18:40	53	45	72	47	48	39	46	点検中
18:50	52	45	71	48	48	39	46	点検中
19:00	52	45	72	47	48	39	46	点検中
19:10	52	45	71	47	48	40	46	点検中
19:20	52	46	71	47	48	39	46	点検中
19:30	52	45	71	47	48	39	46	点検中
19:40	53	45	72	47	48	39	46	点検中
19:50	53	45	72	48	48	39	46	点検中
20:00	53	45	71	48	48	39	46	点検中
20:10	53	45	72	47	48	39	46	点検中
20:20	53	45	71	48	48	40	46	点検中
20:30	53	45	71	47	48	40	46	点検中
20:40	53	45	71	47	48	40	46	点検中
20:50	53	45	71	48	48	40	46	点検中
21:00	52	45	71	48	48	40	46	点検中
21:10	52	45	71	49	48	40	46	点検中
21:20	53	45	72	47	49	40	46	点検中
21:30	53	45	70	48	48	40	46	点検中
21:40	53	45	72	48	48	39	46	点検中
21:50	53	45	71	49	48	40	46	点検中
22:00	52	46	72	49	48	40	46	点検中
22:10	53	46	71	48	48	39	46	点検中
22:20	53	45	72	48	49	40	46	点検中
22:30	53	45	72	48	47	41	46	点検中
22:40	53	46	71	49	48	40	46	点検中
22:50	53	46	71	48	48	40	45	点検中
23:00	53	46	71	48	48	40	46	点検中
23:10	53	45	72	49	49	40	46	点検中
23:20	53	46	71	47	48	40	46	点検中
23:30	53	46	72	49	49	40	47	点検中
23:40	53	46	72	49	49	39	46	点検中
23:50	54	46	72	48	49	40	47	点検中
0:00	53	46	71	48	48	40	47	点検中

茨城県の放射線量の状況について(3月18日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	47	72	48	49	40	47	点検中
0:20	53	46	72	48	50	40	47	点検中
0:30	53	46	72	49	48	40	47	点検中
0:40	53	46	72	49	48	40	47	点検中
0:50	54	46	72	49	48	40	47	点検中
1:00	53	46	71	48	48	39	47	点検中
1:10	53	46	71	49	49	40	47	点検中
1:20	53	46	71	48	49	40	47	点検中
1:30	53	46	71	49	49	40	47	点検中
1:40	53	46	71	49	49	40	47	点検中
1:50	53	46	72	49	49	40	47	点検中
2:00	53	46	72	49	49	40	47	点検中
2:10	53	46	72	48	49	40	48	点検中
2:20	54	46	72	49	49	40	47	点検中
2:30	54	46	72	49	49	40	48	点検中
2:40	53	46	72	49	49	40	48	点検中
2:50	53	47	72	49	48	40	47	点検中
3:00	54	47	72	48	49	40	47	点検中
3:10	54	47	72	49	50	41	48	点検中
3:20	54	47	72	49	49	41	47	点検中
3:30	54	47	72	49	50	41	47	点検中
3:40	53	47	72	49	49	41	48	点検中
3:50	54	47	72	49	49	41	47	点検中
4:00	54	46	72	49	49	40	47	点検中
4:10	54	47	72	50	49	41	48	点検中
4:20	54	47	72	49	50	41	48	点検中
4:30	54	46	72	49	50	41	47	点検中
4:40	55	47	72	49	50	41	47	点検中
4:50	54	47	72	50	50	42	47	点検中
5:00	54	47	72	49	49	41	47	点検中
5:10	53	46	73	49	50	41	47	点検中
5:20	54	46	71	49	50	40	48	点検中
5:30	54	46	72	49	50	41	47	点検中
5:40	55	47	72	49	49	41	48	点検中
5:50	55	47	72	49	49	42	48	点検中
6:00	54	48	73	50	49	41	48	点検中
6:10	55	47	72	49	50	41	48	点検中
6:20	54	47	73	49	50	41	47	点検中
6:30	54	47	72	50	49	41	48	点検中
6:40	54	47	72	49	49	41	48	点検中
6:50	54	47	73	50	49	41	48	点検中
7:00	54	47	73	49	49	41	48	点検中
7:10	54	47	72	49	49	41	48	点検中
7:20	55	48	72	49	50	41	47	点検中
7:30	54	47	73	49	50	42	48	点検中
7:40	54	48	72	48	50	42	48	点検中
7:50	54	47	72	48	49	41	47	点検中
8:00	54	47	72	48	50	42	48	点検中
8:10	53	47	72	49	50	42	47	点検中
8:20	53	48	72	49	49	41	47	点検中
8:30	53	47	72	48	48	41	47	点検中
8:40	53	47	72	49	49	41	46	点検中
8:50	53	46	72	48	49	41	47	点検中
9:00	53	46	72	48	48	40	47	点検中
9:10	54	46	72	48	48	41	46	点検中
9:20	54	46	72	49	49	40	47	点検中
9:30	53	46	72	49	49	40	47	点検中
9:40	53	46	71	48	49	41	47	点検中
9:50	53	46	71	48	49	40	47	点検中
10:00	53	46	72	48	49	40	47	点検中
10:10	53	46	71	48	49	40	47	点検中
10:20	53	46	71	49	49	40	47	点検中
10:30	53	46	71	48	49	40	46	点検中
10:40	53	46	72	48	48	40	47	点検中
10:50	53	46	71	48	49	40	46	点検中
11:00	53	45	72	48	48	40	46	点検中
11:10	53	46	72	48	48	40	46	点検中
11:20	53	46	72	48	48	40	47	点検中
11:30	52	46	71	48	48	40	47	点検中
11:40	51	46	71	48	49	40	47	点検中
11:50	53	46	71	48	48	40	47	点検中
12:00	53	46	72	48	48	40	47	点検中

茨城県の放射線量の状況について(3月18日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	46	72	48	48	41	46	点検中
12:20	53	47	71	48	49	40	47	点検中
12:30	53	46	72	48	49	40	47	点検中
12:40	53	46	72	48	49	40	47	点検中
12:50	53	46	72	48	48	40	47	点検中
13:00	53	46	71	48	48	40	47	点検中
13:10	52	46	72	48	49	40	46	点検中
13:20	53	46	72	47	49	40	47	点検中
13:30	53	46	72	48	48	40	46	点検中
13:40	53	46	72	49	49	40	46	点検中
13:50	52	46	72	48	48	40	46	点検中
14:00	52	46	71	48	48	40	47	点検中
14:10	53	46	71	48	49	40	46	点検中
14:20	53	45	71	48	49	40	46	点検中
14:30	53	46	71	48	48	41	46	点検中
14:40	52	46	71	48	48	40	46	点検中
14:50	53	45	71	48	48	40	47	点検中
15:00	53	45	72	48	48	40	47	点検中
15:10	53	46	71	48	48	40	46	点検中
15:20	53	46	72	48	49	40	46	点検中
15:30	52	46	71	47	48	40	46	点検中
15:40	53	46	72	48	48	40	47	点検中
15:50	53	46	72	48	48	40	46	点検中
16:00	53	45	72	48	48	40	45	点検中
16:10	52	46	71	49	48	40	46	点検中
16:20	53	46	71	48	49	40	46	点検中
16:30	53	45	71	48	48	40	46	点検中
16:40	53	46	72	48	49	40	46	点検中
16:50	53	46	71	48	48	40	46	点検中
17:00	53	46	72	48	48	39	46	点検中
17:10	53	46	72	49	48	41	46	点検中
17:20	53	46	71	48	48	40	46	点検中
17:30	52	45	72	48	48	40	46	点検中
17:40	53	46	72	48	49	41	46	点検中
17:50	53	46	71	48	48	40	46	点検中
18:00	52	46	71	48	48	40	46	点検中
18:10	52	45	72	48	48	40	47	点検中
18:20	53	45	71	48	48	40	46	点検中
18:30	53	45	71	48	48	40	46	点検中
18:40	53	46	72	48	49	40	46	点検中
18:50	53	46	71	48	48	40	46	点検中
19:00	53	46	71	48	48	40	47	点検中
19:10	53	45	71	48	48	40	46	点検中
19:20	53	46	71	48	49	40	46	点検中
19:30	53	46	71	48	49	40	46	点検中
19:40	53	46	71	48	48	40	47	点検中
19:50	53	45	72	48	48	40	47	点検中
20:00	53	46	72	48	48	40	47	点検中
20:10	53	45	71	48	49	40	47	点検中
20:20	53	45	71	48	48	39	46	点検中
20:30	52	46	71	49	49	40	46	点検中
20:40	53	46	72	48	48	40	45	点検中
20:50	53	46	72	48	49	40	47	点検中
21:00	53	46	72	48	48	40	46	点検中
21:10	53	45	71	48	48	40	45	点検中
21:20	53	46	72	48	48	40	46	点検中
21:30	53	46	72	48	49	40	46	点検中
21:40	53	46	72	48	49	40	46	点検中
21:50	53	46	72	48	48	40	46	点検中
22:00	53	46	72	48	48	40	47	点検中
22:10	52	47	72	48	48	40	46	点検中
22:20	52	46	72	48	49	40	47	点検中
22:30	54	46	71	48	49	40	46	点検中
22:40	53	46	72	48	48	41	46	点検中
22:50	53	46	72	48	49	41	46	点検中
23:00	53	46	72	48	49	40	46	点検中
23:10	53	46	71	47	49	40	46	点検中
23:20	53	46	72	48	49	40	47	点検中
23:30	53	46	71	48	48	41	46	点検中
23:40	53	46	72	48	49	41	46	点検中
23:50	53	46	71	48	49	40	46	点検中
0:00	53	46	71	48	49	40	46	点検中

茨城県の放射線量の状況について(3月19日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	46	71	49	48	41	47	点検中
0:20	53	45	71	48	48	40	46	点検中
0:30	52	47	71	48	48	40	46	点検中
0:40	53	46	72	48	48	41	46	点検中
0:50	53	47	72	48	49	41	46	点検中
1:00	53	46	72	48	48	41	46	点検中
1:10	53	46	72	48	49	41	46	点検中
1:20	53	46	72	49	49	41	46	点検中
1:30	53	47	72	49	49	41	47	点検中
1:40	54	48	72	48	49	42	48	点検中
1:50	55	48	73	50	50	43	48	点検中
2:00	56	49	73	52	50	42	50	点検中
2:10	57	51	75	52	52	44	50	点検中
2:20	58	52	75	54	53	46	53	点検中
2:30	59	54	77	55	54	47	53	点検中
2:40	60	54	79	56	55	49	54	点検中
2:50	62	55	78	57	56	50	56	点検中
3:00	63	57	79	58	56	50	56	点検中
3:10	63	57	80	59	56	51	56	点検中
3:20	63	58	80	58	57	51	57	点検中
3:30	63	58	80	59	56	52	57	点検中
3:40	64	57	81	58	57	53	57	点検中
3:50	63	56	81	59	56	51	56	点検中
4:00	63	57	80	57	57	50	56	点検中
4:10	62	55	78	57	55	50	55	点検中
4:20	60	53	77	55	54	48	54	点検中
4:30	59	52	76	54	54	47	52	点検中
4:40	57	51	75	53	52	46	52	点検中
4:50	57	50	74	52	51	45	51	点検中
5:00	57	50	75	52	52	45	50	点検中
5:10	57	50	74	52	52	45	50	点検中
5:20	57	50	73	51	52	44	49	点検中
5:30	57	50	73	51	52	43	49	点検中
5:40	56	49	74	51	52	43	48	点検中
5:50	56	49	73	51	51	43	48	点検中
6:00	55	49	73	51	51	43	48	点検中
6:10	55	48	72	50	51	42	47	点検中
6:20	55	47	72	49	50	42	47	点検中
6:30	54	47	72	49	50	42	46	点検中
6:40	54	47	72	48	50	41	46	点検中
6:50	54	48	71	49	49	41	47	点検中
7:00	53	47	72	48	50	41	46	点検中
7:10	53	46	72	48	49	41	46	点検中
7:20	54	46	72	48	49	41	47	点検中
7:30	54	47	72	49	50	40	46	点検中
7:40	54	46	72	49	49	40	46	点検中
7:50	54	46	71	48	50	41	47	点検中
8:00	53	47	71	49	49	40	48	点検中
8:10	54	46	72	49	49	41	47	点検中
8:20	53	46	71	49	50	40	47	点検中
8:30	53	46	71	49	49	40	47	点検中
8:40	53	46	72	49	48	40	46	点検中
8:50	52	46	72	48	49	40	47	点検中
9:00	53	46	71	48	49	41	47	点検中
9:10	53	46	71	47	49	40	47	点検中
9:20	53	46	71	48	48	40	47	点検中
9:30	53	46	71	48	48	40	47	点検中
9:40	53	46	71	48	49	40	46	点検中
9:50	53	46	72	48	48	40	47	点検中
10:00	52	46	71	48	48	40	46	点検中
10:10	51	46	71	48	48	40	47	点検中
10:20	52	46	72	48	48	40	45	点検中
10:30	52	46	71	48	48	40	47	点検中
10:40	52	46	71	47	48	40	47	点検中
10:50	51	46	72	48	48	40	47	点検中
11:00	52	47	70	47	48	40	46	点検中
11:10	52	46	71	47	48	40	46	点検中
11:20	51	45	72	47	48	40	46	点検中
11:30	52	46	71	47	49	40	46	点検中
11:40	52	46	71	48	48	40	46	点検中
11:50	51	46	71	48	48	40	46	点検中
12:00	52	45	71	47	49	39	47	点検中

茨城県の放射線量の状況について(3月19日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	52	45	71	47	48	40	46	点検中
12:20	53	45	71	48	48	40	47	点検中
12:30	53	45	71	47	48	40	46	点検中
12:40	52	45	71	47	48	40	46	点検中
12:50	53	45	71	48	49	39	46	点検中
13:00	53	46	71	47	48	40	46	点検中
13:10	53	46	72	48	49	40	46	点検中
13:20	53	46	72	48	49	40	46	点検中
13:30	53	46	72	48	48	40	46	点検中
13:40	53	46	71	48	48	39	46	点検中
13:50	53	46	72	48	49	40	48	点検中
14:00	56	47	74	49	49	41	50	点検中
14:10	57	48	75	52	52	44	52	点検中
14:20	59	50	76	53	52	46	55	点検中
14:30	59	51	78	55	53	46	56	点検中
14:40	60	52	78	55	54	47	56	点検中
14:50	61	53	80	56	54	48	57	点検中
15:00	62	53	80	57	55	50	57	点検中
15:10	64	54	81	57	55	52	58	点検中
15:20	65	56	81	59	56	52	59	点検中
15:30	66	57	83	61	58	54	60	点検中
15:40	67	58	83	61	58	55	61	点検中
15:50	67	59	83	62	59	55	61	点検中
16:00	67	59	84	62	59	57	60	点検中
16:10	68	61	85	62	59	56	61	点検中
16:20	67	60	85	62	60	57	61	点検中
16:30	67	59	84	62	60	56	60	点検中
16:40	67	60	84	62	59	55	60	点検中
16:50	66	59	83	61	58	54	60	点検中
17:00	64	57	81	60	57	53	58	点検中
17:10	63	57	81	59	57	52	57	点検中
17:20	63	57	80	60	57	52	57	点検中
17:30	64	56	80	59	57	51	57	点検中
17:40	63	57	80	58	58	51	57	点検中
17:50	61	55	79	57	56	50	55	点検中
18:00	60	53	77	56	54	48	53	点検中
18:10	60	52	76	54	53	45	53	点検中
18:20	58	50	76	53	53	45	51	点検中
18:30	57	49	74	52	52	43	50	点検中
18:40	56	48	73	51	52	43	49	点検中
18:50	55	48	72	50	50	42	49	点検中
19:00	55	48	73	50	51	42	48	点検中
19:10	54	46	71	49	50	41	47	点検中
19:20	54	47	72	49	49	41	47	点検中
19:30	53	46	72	48	49	41	47	点検中
19:40	54	46	71	49	49	41	47	点検中
19:50	53	46	71	48	48	40	46	点検中
20:00	53	46	71	48	49	40	47	点検中
20:10	53	46	71	48	49	40	46	点検中
20:20	52	45	70	48	49	40	47	点検中
20:30	53	45	71	48	49	39	46	点検中
20:40	53	46	70	48	49	40	46	点検中
20:50	53	46	71	48	48	39	46	点検中
21:00	53	45	71	48	49	39	47	点検中
21:10	52	46	71	48	48	39	46	点検中
21:20	53	46	71	48	49	39	46	点検中
21:30	53	46	71	48	49	40	46	点検中
21:40	53	45	71	48	48	39	46	点検中
21:50	52	45	71	47	48	40	45	点検中
22:00	53	46	70	48	48	39	46	点検中
22:10	53	45	71	48	49	39	46	点検中
22:20	53	46	70	47	49	40	46	点検中
22:30	52	46	71	47	49	39	46	点検中
22:40	52	45	70	48	48	40	46	点検中
22:50	53	46	71	47	49	40	46	点検中
23:00	53	45	71	48	49	40	46	点検中
23:10	53	46	70	47	49	39	46	点検中
23:20	53	46	71	48	49	40	46	点検中
23:30	53	46	70	47	49	40	45	点検中
23:40	53	45	71	47	49	40	46	点検中
23:50	53	46	71	48	49	40	46	点検中
0:00	53	46	71	48	48	40	46	点検中

茨城県の放射線量の状況について(3月20日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	46	71	48	49	39	46	点検中
0:20	53	45	70	48	49	40	47	点検中
0:30	54	46	72	47	48	40	46	点検中
0:40	53	46	71	48	48	40	47	点検中
0:50	53	45	71	47	49	40	46	点検中
1:00	52	45	71	48	48	40	46	点検中
1:10	53	46	71	48	49	40	46	点検中
1:20	53	46	70	48	49	40	46	点検中
1:30	53	46	71	48	48	40	46	点検中
1:40	53	46	71	48	48	40	46	点検中
1:50	52	45	70	48	48	40	46	点検中
2:00	52	45	71	48	48	40	46	点検中
2:10	53	46	71	47	48	39	46	点検中
2:20	53	46	70	47	48	40	45	点検中
2:30	53	46	70	47	49	40	46	点検中
2:40	52	46	70	47	48	40	45	点検中
2:50	53	45	71	47	48	39	46	点検中
3:00	52	45	70	48	48	40	46	点検中
3:10	53	45	70	47	49	40	46	点検中
3:20	52	46	70	47	48	39	46	点検中
3:30	53	45	71	47	48	39	46	点検中
3:40	53	46	71	48	49	40	45	点検中
3:50	53	45	70	48	49	40	46	点検中
4:00	53	45	71	48	48	39	46	点検中
4:10	53	45	70	48	48	40	45	点検中
4:20	53	45	71	47	49	39	46	点検中
4:30	53	46	71	47	48	39	46	点検中
4:40	53	45	71	48	49	40	46	点検中
4:50	54	46	70	48	49	39	45	点検中
5:00	53	46	71	48	49	39	46	点検中
5:10	54	46	71	48	49	39	46	点検中
5:20	53	45	70	48	49	40	45	点検中
5:30	54	47	71	48	49	39	46	点検中
5:40	53	46	71	48	48	40	46	点検中
5:50	53	46	71	48	49	40	46	点検中
6:00	53	46	71	48	48	40	46	点検中
6:10	53	46	71	47	48	40	46	点検中
6:20	53	46	71	47	49	40	46	点検中
6:30	53	46	71	47	49	40	46	点検中
6:40	53	46	71	47	49	40	46	点検中
6:50	53	46	71	47	49	40	45	点検中
7:00	52	46	71	47	48	40	46	点検中
7:10	53	46	71	47	48	39	46	点検中
7:20	52	45	71	47	48	40	45	点検中
7:30	52	45	71	47	48	40	45	点検中
7:40	52	44	70	47	47	39	45	点検中
7:50	52	44	70	47	48	39	44	点検中
8:00	52	45	71	47	47	39	44	点検中
8:10	53	45	71	47	48	39	44	点検中
8:20	52	45	71	47	48	39	44	点検中
8:30	52	44	71	47	48	40	45	点検中
8:40	52	45	70	47	47	39	44	点検中
8:50	52	45	71	47	47	39	44	点検中
9:00	50	44	70	47	48	39	44	点検中
9:10	51	44	71	46	48	39	44	点検中
9:20	51	44	71	47	48	39	44	点検中
9:30	51	44	70	47	47	39	44	点検中
9:40	51	45	71	47	48	39	44	点検中
9:50	52	45	71	47	48	39	44	点検中
10:00	52	45	70	47	48	39	44	点検中
10:10	52	45	71	47	48	39	44	点検中
10:20	52	45	71	47	47	39	44	点検中
10:30	52	45	71	47	48	39	44	点検中
10:40	51	45	71	47	48	40	44	点検中
10:50	51	44	71	47	48	40	44	点検中
11:00	52	45	71	47	48	40	44	点検中
11:10	52	45	71	47	47	40	44	点検中
11:20	52	45	71	46	47	40	44	点検中
11:30	52	45	71	47	47	40	44	点検中
11:40	52	45	70	47	47	39	45	点検中
11:50	53	45	70	48	48	40	44	点検中
12:00	52	46	71	47	48	40	44	点検中

茨城県の放射線量の状況について(3月20日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	52	45	71	47	48	39	45	点検中
12:20	52	46	70	47	47	39	44	点検中
12:30	52	45	71	47	48	40	44	点検中
12:40	53	45	71	47	47	39	44	点検中
12:50	53	45	71	47	47	39	44	点検中
13:00	52	44	71	47	48	39	44	点検中
13:10	52	45	71	47	48	39	44	点検中
13:20	53	45	71	47	48	39	45	点検中
13:30	52	45	71	46	48	39	45	点検中
13:40	52	45	71	46	48	39	45	点検中
13:50	53	45	71	47	48	39	45	点検中
14:00	52	45	71	47	48	39	45	点検中
14:10	52	45	71	47	48	39	45	点検中
14:20	52	45	71	47	48	39	45	点検中
14:30	51	45	71	47	48	39	45	点検中
14:40	52	45	71	47	48	40	45	点検中
14:50	52	45	72	47	48	39	46	点検中
15:00	52	45	70	47	48	39	45	点検中
15:10	53	45	71	47	48	40	46	点検中
15:20	52	45	71	47	49	40	45	点検中
15:30	53	45	71	47	48	39	45	点検中
15:40	52	45	71	47	48	39	45	点検中
15:50	52	45	71	47	48	39	45	点検中
16:00	53	45	71	47	48	39	45	点検中
16:10	51	44	71	47	48	40	45	点検中
16:20	52	46	71	47	48	39	45	点検中
16:30	52	45	71	47	48	39	45	点検中
16:40	51	45	71	47	48	40	45	点検中
16:50	52	45	71	47	47	39	45	点検中
17:00	52	45	70	48	48	39	45	点検中
17:10	52	45	71	48	48	39	45	点検中
17:20	52	45	71	48	48	39	46	点検中
17:30	52	45	71	47	48	40	46	点検中
17:40	52	45	71	47	48	40	45	点検中
17:50	53	45	71	48	48	39	45	点検中
18:00	52	45	72	47	48	39	46	点検中
18:10	52	45	71	47	48	40	45	点検中
18:20	53	45	71	47	48	40	46	点検中
18:30	53	45	71	48	48	40	46	点検中
18:40	52	45	71	48	49	39	46	点検中
18:50	53	45	72	47	48	39	46	点検中
19:00	52	45	70	47	49	39	45	点検中
19:10	53	45	71	48	48	39	46	点検中
19:20	53	46	72	47	48	39	45	点検中
19:30	52	46	71	48	49	39	46	点検中
19:40	52	44	71	48	49	40	46	点検中
19:50	53	45	71	48	48	39	46	点検中
20:00	52	45	71	47	48	39	46	点検中
20:10	53	45	71	47	48	39	45	点検中
20:20	52	45	71	47	48	40	46	点検中
20:30	52	45	70	47	48	39	45	点検中
20:40	53	45	71	48	48	40	46	点検中
20:50	53	45	71	47	48	40	46	点検中
21:00	52	45	71	48	48	39	46	点検中
21:10	51	45	70	47	48	39	45	点検中
21:20	52	45	71	47	48	39	46	点検中
21:30	52	45	71	48	49	40	46	点検中
21:40	53	44	71	48	49	39	46	点検中
21:50	52	45	71	48	48	39	46	点検中
22:00	52	45	71	48	48	39	46	点検中
22:10	53	45	71	48	48	39	46	点検中
22:20	52	45	71	48	48	39	45	点検中
22:30	52	45	70	47	49	40	46	点検中
22:40	53	45	71	48	48	39	46	点検中
22:50	53	45	70	47	48	39	46	点検中
23:00	52	45	71	48	48	39	47	点検中
23:10	53	46	71	49	48	40	47	点検中
23:20	52	45	71	47	48	40	46	点検中
23:30	52	45	70	48	49	39	46	点検中
23:40	53	45	71	48	49	39	46	点検中
23:50	53	45	72	48	48	40	46	点検中
0:00	53	45	71	48	49	40	46	点検中

茨城県の放射線量の状況について(3月21日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	53	45	71	49	48	39	46	点検中
0:20	53	46	71	49	48	40	46	点検中
0:30	53	46	72	48	49	40	46	点検中
0:40	53	45	71	48	49	40	46	点検中
0:50	53	46	71	49	48	40	46	点検中
1:00	53	46	71	49	49	40	46	点検中
1:10	53	46	71	48	49	39	47	点検中
1:20	53	46	71	48	49	40	47	点検中
1:30	53	46	71	49	49	39	47	点検中
1:40	53	46	72	48	49	40	47	点検中
1:50	54	47	71	48	49	40	46	点検中
2:00	53	46	71	49	49	40	47	点検中
2:10	53	46	71	48	49	39	47	点検中
2:20	53	47	71	49	49	40	46	点検中
2:30	54	46	71	49	49	40	47	点検中
2:40	54	46	71	48	49	40	47	点検中
2:50	54	46	70	49	49	40	47	点検中
3:00	53	46	71	49	49	40	47	点検中
3:10	53	46	71	49	49	40	47	点検中
3:20	54	47	71	49	49	41	47	点検中
3:30	53	46	70	48	49	40	46	点検中
3:40	54	47	71	49	49	40	46	点検中
3:50	53	46	72	48	49	40	46	点検中
4:00	52	46	72	48	48	40	46	点検中
4:10	54	46	72	48	49	41	46	点検中
4:20	53	46	71	48	49	40	47	点検中
4:30	54	47	71	48	49	40	47	点検中
4:40	53	46	71	48	49	40	47	点検中
4:50	54	46	72	48	49	40	46	点検中
5:00	53	46	71	48	49	40	47	点検中
5:10	53	47	71	48	49	40	47	点検中
5:20	52	46	71	48	48	40	47	点検中
5:30	53	46	71	48	48	40	46	点検中
5:40	53	46	71	48	49	40	47	点検中
5:50	53	46	71	48	48	40	47	点検中
6:00	54	46	71	48	48	40	46	点検中
6:10	53	46	71	48	49	40	47	点検中
6:20	53	46	71	49	48	40	47	点検中
6:30	54	46	72	49	48	40	47	点検中
6:40	53	46	72	49	50	40	47	点検中
6:50	53	46	72	48	49	41	47	点検中
7:00	54	46	72	48	49	41	47	点検中
7:10	54	47	71	48	49	41	46	点検中
7:20	53	47	71	49	49	40	47	点検中
7:30	54	46	72	49	49	40	47	点検中
7:40	53	46	71	49	49	41	47	点検中
7:50	53	46	72	48	49	40	46	点検中
8:00	54	46	72	48	49	40	46	点検中
8:10	53	46	71	48	48	41	47	点検中
8:20	55	46	72	48	49	40	47	点検中
8:30	53	46	71	48	48	40	46	点検中
8:40	54	46	72	49	49	40	47	点検中
8:50	53	46	72	48	49	40	47	点検中
9:00	53	45	71	48	49	40	46	点検中
9:10	53	46	71	49	49	40	47	点検中
9:20	53	46	71	48	49	40	46	点検中
9:30	52	45	71	48	48	40	47	点検中
9:40	54	46	71	48	48	40	46	点検中
9:50	53	46	72	48	48	40	46	点検中
10:00	53	46	71	47	48	40	46	点検中
10:10	53	45	71	48	49	40	46	点検中
10:20	53	45	71	48	49	40	46	点検中
10:30	53	46	70	48	49	39	46	点検中
10:40	53	46	71	48	48	40	47	点検中
10:50	53	46	72	48	48	40	46	点検中
11:00	53	46	72	49	49	40	46	点検中
11:10	53	46	71	47	48	40	46	点検中
11:20	53	46	71	47	48	40	46	点検中
11:30	53	45	71	48	49	40	46	点検中
11:40	53	46	71	48	48	40	46	点検中
11:50	53	46	72	48	48	40	47	点検中
12:00	54	46	71	48	49	39	47	点検中

茨城県の放射線量の状況について(3月21日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	45	71	48	48	40	46	点検中
12:20	53	45	72	48	49	40	47	点検中
12:30	53	46	71	48	49	40	46	点検中
12:40	52	46	71	48	49	40	46	点検中
12:50	52	46	71	48	48	40	46	点検中
13:00	53	46	71	48	49	40	46	点検中
13:10	53	46	71	48	48	40	46	点検中
13:20	53	46	72	48	48	40	46	点検中
13:30	53	46	71	47	48	40	46	点検中
13:40	53	46	72	47	49	40	46	点検中
13:50	52	46	71	48	48	40	46	点検中
14:00	53	46	71	48	48	40	46	点検中
14:10	53	45	71	48	49	39	46	点検中
14:20	53	45	71	48	48	39	46	点検中
14:30	52	46	72	48	48	40	46	点検中
14:40	52	46	72	48	48	40	46	点検中
14:50	53	46	71	48	49	40	46	点検中
15:00	53	46	71	47	48	39	46	点検中
15:10	53	46	72	47	48	40	46	点検中
15:20	53	45	71	48	48	40	46	点検中
15:30	53	46	71	48	48	40	47	点検中
15:40	52	46	71	48	49	39	46	点検中
15:50	53	46	71	47	48	39	46	点検中
16:00	53	45	71	47	49	40	46	点検中
16:10	53	46	71	48	48	40	46	点検中
16:20	54	45	71	48	48	40	46	点検中
16:30	53	46	71	48	49	40	46	点検中
16:40	53	45	71	48	48	40	46	点検中
16:50	52	46	72	48	48	40	46	点検中
17:00	53	46	71	47	48	40	46	点検中
17:10	53	45	71	48	48	40	46	点検中
17:20	53	46	71	48	49	40	45	点検中
17:30	52	46	70	48	49	39	46	点検中
17:40	52	45	72	47	48	39	46	点検中
17:50	52	45	71	48	48	40	46	点検中
18:00	53	45	71	48	48	40	46	点検中
18:10	53	46	72	48	48	40	47	点検中
18:20	53	45	71	48	49	39	46	点検中
18:30	53	45	71	48	48	39	46	点検中
18:40	53	46	71	47	49	40	46	点検中
18:50	52	45	72	47	49	39	46	点検中
19:00	54	45	71	48	48	39	46	点検中
19:10	54	45	71	47	48	39	46	点検中
19:20	52	45	71	48	48	40	47	点検中
19:30	53	45	71	48	48	40	46	点検中
19:40	52	45	71	48	48	40	46	点検中
19:50	53	44	72	48	49	39	46	点検中
20:00	53	45	71	48	49	40	46	点検中
20:10	53	46	71	48	48	39	46	点検中
20:20	54	45	71	48	48	39	46	点検中
20:30	53	45	71	48	49	40	46	点検中
20:40	53	46	71	48	48	40	46	点検中
20:50	53	46	71	48	48	40	46	点検中
21:00	52	46	71	48	49	40	46	点検中
21:10	53	46	71	48	49	40	46	点検中
21:20	53	46	72	48	49	40	46	点検中
21:30	53	46	71	48	48	41	46	点検中
21:40	53	45	71	48	48	40	46	点検中
21:50	54	46	71	48	48	40	47	点検中
22:00	53	46	71	48	49	41	46	点検中
22:10	53	46	71	48	49	40	47	点検中
22:20	54	46	71	48	49	40	47	点検中
22:30	54	46	71	49	49	40	47	点検中
22:40	54	46	72	48	49	40	47	点検中
22:50	53	46	72	48	49	40	47	点検中
23:00	54	46	72	49	49	40	46	点検中
23:10	54	46	71	48	49	40	46	点検中
23:20	54	47	72	48	49	41	46	点検中
23:30	54	46	72	49	49	40	46	点検中
23:40	53	47	72	49	49	40	47	点検中
23:50	53	46	71	49	50	40	47	点検中
0:00	54	47	71	49	49	40	46	点検中

茨城県の放射線量の状況について(3月22日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
0:10	54	47	71	49	49	40	47	点検中
0:20	54	46	71	49	49	40	47	点検中
0:30	54	47	71	48	50	41	47	点検中
0:40	53	47	72	48	49	40	46	点検中
0:50	54	47	71	49	49	40	47	点検中
1:00	54	47	72	49	49	41	47	点検中
1:10	54	47	72	49	49	40	47	点検中
1:20	54	47	71	49	48	41	47	点検中
1:30	54	47	71	48	48	41	47	点検中
1:40	54	46	72	49	49	41	47	点検中
1:50	54	47	72	49	49	40	46	点検中
2:00	55	47	71	49	49	41	47	点検中
2:10	54	47	72	49	49	41	47	点検中
2:20	54	48	72	48	49	42	46	点検中
2:30	54	47	72	49	50	41	47	点検中
2:40	54	47	72	49	50	41	47	点検中
2:50	54	47	71	49	49	40	46	点検中
3:00	54	47	72	49	50	41	47	点検中
3:10	54	47	72	49	50	41	48	点検中
3:20	54	46	72	50	50	41	47	点検中
3:30	54	47	71	50	49	41	47	点検中
3:40	55	47	72	49	50	40	47	点検中
3:50	54	47	71	49	50	41	47	点検中
4:00	54	47	72	49	49	40	46	点検中
4:10	54	46	72	48	49	41	47	点検中
4:20	54	46	72	49	49	40	47	点検中
4:30	55	47	73	49	50	41	47	点検中
4:40	54	47	72	48	49	40	47	点検中
4:50	55	47	72	49	50	41	48	点検中
5:00	54	47	73	49	50	40	47	点検中
5:10	54	47	72	49	49	40	47	点検中
5:20	54	47	72	49	49	41	47	点検中
5:30	54	47	72	49	50	41	47	点検中
5:40	54	47	72	49	50	41	48	点検中
5:50	54	47	72	49	50	40	47	点検中
6:00	54	46	72	49	50	41	47	点検中
6:10	55	47	72	50	50	41	47	点検中
6:20	54	48	73	49	49	41	47	点検中
6:30	55	47	71	49	50	41	47	点検中
6:40	54	48	72	48	50	40	48	点検中
6:50	54	47	72	49	50	41	47	点検中
7:00	54	47	73	50	50	41	47	点検中
7:10	54	48	73	49	50	41	47	点検中
7:20	55	47	72	49	50	40	46	点検中
7:30	54	48	72	49	50	40	47	点検中
7:40	55	47	72	49	49	41	47	点検中
7:50	54	48	71	49	50	41	47	点検中
8:00	54	48	72	49	50	41	47	点検中
8:10	54	47	72	48	50	41	47	点検中
8:20	54	46	72	49	50	40	47	点検中
8:30	54	46	72	48	49	40	47	点検中
8:40	54	47	72	48	49	41	47	点検中
8:50	54	46	72	48	49	41	47	点検中
9:00	54	46	71	48	49	40	47	点検中
9:10	54	47	71	48	49	40	46	点検中
9:20	54	46	72	48	49	40	46	点検中
9:30	53	46	71	48	48	40	46	点検中
9:40	54	47	72	49	49	40	46	点検中
9:50	54	47	71	49	50	40	46	点検中
10:00	53	46	72	48	49	40	47	点検中
10:10	53	46	72	48	49	40	47	点検中
10:20	54	46	71	48	49	40	46	点検中
10:30	53	46	71	48	48	40	46	点検中
10:40	53	46	72	48	48	41	46	点検中
10:50	53	46	72	48	49	40	46	点検中
11:00	53	46	72	48	49	40	46	点検中
11:10	53	46	71	48	48	40	46	点検中
11:20	52	46	72	47	49	40	47	点検中
11:30	54	46	71	48	49	40	46	点検中
11:40	53	46	71	48	48	40	46	点検中
11:50	53	46	72	48	49	41	47	点検中
12:00	53	46	72	48	49	40	46	点検中

茨城県の放射線量の状況について(3月22日)
(固定観測局(那珂市))

時刻	那珂市							
	横堀	門部	菅谷	本米崎	額田	鴻巣	後台	瓜連
12:10	53	46	72	48	49	40	46	点検中
12:20	53	46	71	48	48	40	46	点検中
12:30	54	45	72	48	48	41	46	点検中
12:40	52	46	72	48	48	40	47	点検中
12:50	53	45	71	48	49	40	47	点検中
13:00	53	46	72	48	48	40	47	点検中
13:10	53	46	72	48	49	40	47	点検中
13:20	53	45	72	48	49	40	47	点検中
13:30	53	46	72	48	48	39	46	点検中
13:40	53	46	72	48	48	40	46	点検中
13:50	53	47	72	48	48	40	47	点検中
14:00	53	46	72	48	49	40	47	点検中
14:10	54	45	72	48	48	41	47	点検中
14:20	53	46	71	48	48	39	46	点検中
14:30	53	46	71	48	49	40	46	点検中
14:40	53	45	72	48	48	39	46	点検中
14:50	53	46	72	48	49	39	46	点検中
15:00	53	46	71	48	49	40	46	点検中
15:10	53	45	71	48	48	40	46	点検中
15:20	53	45	72	48	48	40	47	点検中
15:30	53	45	71	48	49	39	45	点検中
15:40	53	45	71	48	48	40	46	点検中
15:50	52	46	71	48	48	40	47	点検中
16:00	52	46	71	48	48	40	46	点検中
16:10	54	45	72	48	48	40	46	点検中
16:20	53	45	71	48	49	40	47	点検中
16:30	53	46	71	48	49	40	47	点検中
16:40	53	45	72	48	49	40	47	点検中
16:50	53	46	71	48	49	40	46	点検中
17:00	53	46	71	48	49	40	47	点検中
17:10	53	46	72	48	49	39	46	点検中
17:20	52	46	71	48	48	40	46	点検中
17:30	53	45	71	48	49	40	47	点検中
17:40	54	46	71	48	48	39	46	点検中
17:50	52	46	71	48	48	40	46	点検中
18:00	53	45	72	48	49	40	46	点検中
18:10	53	46	72	48	49	40	46	点検中
18:20	53	45	71	47	49	40	46	点検中
18:30	53	45	71	48	48	40	46	点検中
18:40	53	46	71	48	48	39	46	点検中
18:50	53	46	71	48	48	40	46	点検中
19:00	53	45	71	48	48	39	46	点検中
19:10	53	46	72	48	48	40	47	点検中
19:20	53	45	72	48	48	40	46	点検中
19:30	53	45	72	48	48	40	46	点検中
19:40	52	45	71	48	47	40	46	点検中
19:50	53	45	72	48	49	39	46	点検中
20:00	53	45	72	49	48	40	46	点検中
20:10	53	45	71	48	48	40	47	点検中
20:20	52	46	71	48	48	40	46	点検中
20:30	52	45	71	48	48	39	47	点検中
20:40	53	45	70	48	48	40	46	点検中
20:50	52	45	71	47	48	40	46	点検中
21:00	53	45	71	47	48	39	46	点検中
21:10	53	46	71	48	48	40	46	点検中
21:20	53	45	71	48	48	41	46	点検中
21:30	53	46	70	47	48	40	47	点検中
21:40	53	45	71	47	48	39	46	点検中
21:50	52	45	71	48	48	40	47	点検中
22:00	53	46	71	47	48	40	46	点検中
22:10	53	46	71	48	48	40	47	点検中
22:20	53	45	71	48	49	40	47	点検中
22:30	53	46	71	48	49	39	46	点検中
22:40	53	46	71	48	49	40	46	点検中
22:50	53	46	71	48	49	40	47	点検中
23:00	54	46	71	48	48	40	47	点検中
23:10	53	46	71	48	49	39	47	点検中
23:20	53	46	72	48	48	40	46	点検中
23:30	54	46	71	48	48	40	46	点検中
23:40	53	45	72	48	49	40	47	点検中
23:50	52	45	71	49	49	40	46	点検中
0:00	53	46	71	49	49	40	46	点検中